

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 17 Page(s) 7121)

Set a stone 15x10x8 ins., 10" in the ground, for cor. to secs. 29, 30, 31 and 32, marked with 5 notches on E. and 1 notch on S. edges, from which

A Laurel 11" dia., bears N.15½°E., 38¼ lks. dist. mkd. T30S R4W S29 BT.

A Fir 14" dia., bears S.66¼°E., 78 lks. dist. mkd. T30S R4W S32 BT.

A Laurel 10" dia., bears S.66 3/4°W., 36 lks. dist. mkd. T30S R4W S31 BT.

A Fir 5" dia., bears N.35°W., 43 lks. dist. mkd. T30S R4W S30 BT.

Survey by John H. Markham, Jr. - Wit: Geo. Vaughn - June 12, 1951 - C.S. Fiel 40/296-5

Location determined from old BT:

A Laurel stump N.15°E., 26.0 ft.

A Fir snag 14" dia. S.66°E., 51.0 ft.

A Laurel 14" dia. S.67°W., 24.0 ft.

At corner found a stone monument. Drove a 1" x 30" pipe alongside stone and marked bearing trees:

Fir 20" dia., N.77°E., 26.0 ft.

Cedar 14" dia., N.15°W., 53.0 ft.

Laurel 24" dia., S.8°W., 26.0 ft.

Fir 18" dia., bears S.25°E., 64 ft.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Feb. 19, 2013 - C.S. File 67/38-18

Found - Possible orig. stone (see description below) is loose and out of position.

1951 corner monument; a 1"x30" pipe now a 1" O.D. x 23" long iron pipe firmly set protruding 10" above ground and leaning approx. 4" NE'ly from plumb. Depression in ground indicates top of pipe. May have been centered over orig. stone position.

Above noted loose stone is N.65°E., 1.5 ft. from top center of fd. IP monument. Stone is 12x9x4" (orig. rec. 15x10x8") and has no discernible markings. No other stones are fd nearby.

NE Laurel and NW Fir now indistinct root-holes fd. near rec. bearing & dist. OBTs

continued next page

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 14" dia., now a mostly rotted away 14" dia., 2 ft. tall fir stump with the scribing "S3" visible on a fragmentary blaze; bears S.64½°E., 51.5 ft (rec. S.66¼°E. 51.5 ft) OBT

A laurel 10" dia., now a dead, intact, 22" dia., madrone with a fully healed single blaze; bears S.66¾°W., 22.5 ft. (rec. S.66¾°W., 23.8 ft. A possible slope measurement) OBT

A fir 20" dia., now rotted away 16" dia., 2 ft. tall fir stump; bears N.83°E., 24.2 ft. (rec. N.77°E., 26.0 ft; possible misread bearing and a good slope dist.) 1951

A cedar 14" dia., now a 19" dia., I.Cedar with a high partially healed, single blaze showing visible but illegible scribing and an attached (to face) BT tag; bears N.16°W., 53.0 ft. (rec. N.15°W., 53.0 ft.) 1951

A fir 18" dia, now a 28" dia., 2 ft. tall fir stump with a rotted center showing evidence of a healed blaze in the bark but blaze face itself would be rottted away; bears S.23½°E., 64.0 ft. (rec. S.25°E., 64.0 ft) 1951

New - Top center position of fd IP is reference out and pipe is removed from ground at referenced position we place a 2½" dia., brass cap on a 1" ID 32" long IP firmly and plumbly set protruding 8" above ground. Fd. 1951 IP is set on south edge of BC monument and protrudes 6". FD possible orig. stone is set on north edge of BC monument & protrudes 3". Brass cap mkd:
 DOUGLAS COUNTY SURVEYORS OFFICE
 T30S R4W

30|29
31|32
 2013

A 9" dia., D.Fir scribed "X""CS BT" on a high-low double blaze; bears N.58½°E., 13.2 ft.

An 11" dia., D.Fir scribed "T30S R4W S32" "CSBT" on a double blaze; bears S.17°E., 9.3 ft.

A 23" dia., pistol butt D.Fir scribed "T30SR4WS32" "CSBT" on a double blaze; bears (to discernible CRC) S.64°W., 18.0 ft.

Note - Monument is on moderately steep westerly slope in old reprod fir forest with scattered cedar and madrone.
 Compass decl. 15½°E.

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2872, surveyed April 2017/Oct. 2019- (DCSO records Vol. 59 Page 23844-5)

The cor of secs. 29, 30, 31, & 32, perpetuated by Markham, in 1951 subsequently perpetuated by Smith, in 2013; monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground (alongside of which is an iron pipe, 1½" dia., firmly set, projecting 6" above the ground), with a brass cap (properly) mkd.

from which the remains of the original BTs

A decayed fir stump, 18" dia., bears S.66¼°E., 51.5 ft., with scribe marks S3 visible on open blaze.

A madrone snag, 28" dia., bears S.66¾°W., 21.6 ft., alongside of which is a down madrone, 28" dia. no marks visible. (Record, 23.8 ft.)

and the remains of the bearing trees mkd. by Markham, Jr.

A decayed fir stump, 16" dia., bears N.81°E., 24.7 ft., no marks visible.

A decayed fir stump, 26" dia., bears S.24½°E., 64.4 ft., no marks visible.

A cedar, 18" dia., bears N.16¼°W., 53.7 ft., with illegible scribe marks visible on partially healed blaze.

and the BTs mkd. by Smith

A fir, 9" dia., bears N.58¼°E., 13.4 ft., with a healed double blaze.

A fir, 11" dia., bears S.20¾°E., 9.3 ft., with a healed double blaze.

A fir, 24" dia., bears S.61½°W., 17.3 ft., with illegible scribe marks visible on partially healed blaze.

NAD 1983 (2011)

Latitude: 42°55'36.19" N. Longitude: 123°12'29.11"W.