

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7003)

Set ¼ sec. post at proper distance, from which
A Laurel 6" dia., bears N.70°E., 30 lks. dist.
A Laurel 4" dia., bears S.30°W., 23 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7080)

Set a Laurel post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on W. face, from which
A Laurel 4" dia., bears S.83°W., 37 lks. dist. mkd. ¼ S BT.
A Laurel 4" dia., bears N.70°E., 10 lks. dist. mkd. ¼ S BT
The old post and bearing trees have been destroyed by fire. Appearances indicate that this locality has been fired more than once, none but small laurels, no larger than 4 ins. in dia. now growing here, with other underbrush of late growth.

Survey by Frederick E. Warner - For: J.H. Baxter & Co. - March/April 1957 - C.S. File 42/257

I find no trace of corner. I restore corner by a proportional measurement.
Set an I.P. 1½" dia., 36" long, 28" in ground, mkd. RS 298, from which
A D.Fir 10" dia., bears S.77°E., 23.10 ft. mkd. ¼ S4 RS 298 BT.
A D.Fir 12" dia., bears S.11°30'W., 29.70 ft. mkd. ¼ S5 RS 298 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - Aug. 1963 - C.S. File 53/26

Found - 1½" I.Pipe at corner and both BTs as recorded, 1957. SE. BT dead. SW. BT down.
New BTs -9" Laurel bears S.23°W., 8.5 ft. scribed ¼ S5 CS BT.
9" W.Fir bears S.39°E., 25.7 ft. scribed ¼ S4 CS BT.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20114-5)

Point for the ¼ sec. cor. of secs. 4 & 5, at proportionate distance; there is no remaining evidence of the orig. corner.
continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set a stainless steel post, 28" long, 2½" diam., 25" in the ground, with brass cap mkd. T30S R4W

1/4

S 5 | S 4

1994

from which

A fir, 15" diam. bears N.76 3/4°E., 19½ lks., mkd. ¼ S4 BT

A fir, 19" diam., bears S.39¼°W., 16 lks., mkd. ¼ S5 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

From this point, a point established as the ¼ sec. cor. of secs. 4 and 5 by Warner, in 1957, perpetuated by Byron, in 1963, bears S.87°42'26"E., 0.285 chs.; monumented with an iron pipe, 1½" diam., firmly set, projecting 6" above ground, from which the remains of bearing trees mkd. by Warner:

A fir snag, 10" diam., bears S.77°E., 35½ lks., with scribe marks ¼ S4 RS298 BT visible on open blaze.

A fir snag, 12" diam., bears S.14°W., 45½ lks., with fragmentary scribe marks visible on open blaze.

and the remains of bearing trees mkd. by Byron

A root hole, bears S.38°E., 39 lks., with decayed trunk, size indeterminate, alongside, with no marks visible.

A madrone, 14" diam., bears S.23 3/4°W., 12½ lks., with healed double blazes.

This point was rejected due to erroneous position and not used in this survey.

Fd. OK by B. Shaner, Nov. 2001 - 2001-0094 A thru C