

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by G.G. Stewart, Deputy Co. Surveyor - Dec. 29, 1922
-C.S. File 7/31; M 2-9; Vol. 3 Pg. 136; C.S. File 7/52

Marked by I. Pipe, from which
12" Fir S.60°E., 5.9 ft.
12" Fir N.18½°W., 37.5 ft.

Survey by Kristian DeGroot - For: Roy Cox and John Ott - Jan.
1990 - M 109-47

Found - 3/4" I.P. firmly set by Stewart in 1922.
26" D.Fir bears N.18°30'W., 37.5 ft. with healed
blaze.
16" rotted D.Fir stump bears S.60°E., 5.9 ft. with
scribe marks visible.

I remove the 3/4" I.P. and replace in the exact same position
a 5/8" x 30" Iron rod with alum. cap mkd.

C
N 1/16 | S15
C

PLS 1941

Reset the original 3/4" I.P. on S. edge of my 5/8" I.R. and
flush with the ground.

New BT - 16" D.Fir bears N.81°30'E., 36.4 ft. scribed "CN
1/16 S15 BT"

Douglas Co. Surveyors Office - Randall Smith and Stephen
Flause, crew - March 8, 1990 - C.S. File 64/6-8

Found - A 5/8" IR w/alum cap protruding 2" above ground.
3/4" I.D. Iron pipe found along South edge of
IR/alum cap 2" under ground.
12" now 26" dia. D.Fir with a fully healed single
blaze bears N.18½°W., 37.5 ft. (agrees w/rec).
Bt will be cut down in near future.

12" now 16" dia. rotted 2 ft. high D.Fir stump with
illegible scribe marks visible, bears S.60°E.,
5.9 ft. (agrees w/rec.)

16" now 16" dia. D.Fir with an unhealed single
blaze, scribing visible "CN 1/16 S15 BT" bears
N.77¼°E., 35.7 ft. (Rec. N.81½°E., 36.4 ft.)

New BTs -5" Madrone, bark scribed "CN 1/16 S15 CS BT" bears
N.9½°E., 6.7 ft.

5" Pine double blazed "CN 1/16 S15 CS BT" bears
S.3°E., 8.4 ft.

5" D.Fir double blazed "CN 1/16 S15 CS BT" bears
S.88°W., 26.6 ft.

Fd. Ok by R. Quimby 1/2007 - 2007-0016 A&B