

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. of Sec. 3 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by John H. Markham, Jr. - Wit: Dennis & Geo. Vaughn -
For: Stomar Lbr. - Nov. 2, 1951 - C.S. File 40/386-1

At the midpoint on the Twp. line between the NW and NE corner
of sec. 3, I drove a 1" x 30" I.P., from which
A Cedar 9" dia., bears S.50°E., 13.0 ft. mkd. ¼S 53 BT.
A Cedar 5" dia., bears S.15°E., 9.0 ft. mkd. ¼S 53 BT.
NW Cor. Sec. 3 bears West 2673 ft.
NE Cor. Sec. 3 bears East 2673 ft.
Sec. Cor. 34 and 35 bears East 342.0 ft.

U.S. Bureau of Land management Administrative survey by Alex
Tupyi - Oct. 1978 - M 81-14

Set 7/8" I.P. 2 ft. long, 18" in ground, from which
A Cedar 8" dia., bears N.68°E., 10.7 ft.
A Cedar 10" dia., bears N.36°W., 3.0 ft.
(New corner bears S.67°49'W., 13.4 ft. from present pipe set
by Markham.)

Fd. OK, Oct. 1992 by Greg Lang - M 117-1

Ron Quimby - For: Roseburg Forest Products - March 1996 -
M 123-58

Set - 5/8" x 30" iron rod with plastic cap marked "AA
SURVEYING, INC" at the corner, from which a:
½" iron pipe bears S.83°54'E., 4.87' with bearing trees
set by Markham per C.S. 40/386. (1951)
7/8" iron pipe bears N.72°54'E., 16.66' with bearing
trees set by BLM per M 81-14 (1978)
New BTs-
15" Madrone bears, S.10°W., 22.5', mkd: "N ¼ S3 BT"
8" Madrone bears, S.86°W., 16.5' mkd: "N ¼ S3 BT"
19" Cedar bears, N.40°W., 3.7', mkd: "N ¼ S3 BT"
8" Cedar bears, N.27°E., 14.3', mkd: "N ¼ S3 BT"

BLM dependent resurvey by Bryan S. Seibold, Cadastral
Surveyor, and Robert Browning, Surveying Technician, under
Group #1686, surveyed May 1993 thru April. 1995 - (DCSO
records Vol. 52 Page(s) 20090)

From the ¼ cor. to sec. 34 only, T29-7
A point established during the course of an administrative
survey as the ¼ sec. cor. of sec. 3 only by Alex Tupyi,
Roseburg District, BLM, in 1978, bears S.86°39'57"E., 34.901
chs.; monumented with an iron pipe, 1" diam., firmly set,
projecting 7" above ground. continued next page

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. of Sec. 3 only,

Alias	Description
Alias	Description
Alias	Description
Alias	Description

From the ¼ corner to sec. 34 only, T29-7
A point established as the ¼ sec. cor. of sec. 3 only by Markham, in 1951, bears S.86°49'00"E., 35.065 chs.; monumented with an iron pipe, 1¼" diam., firmly set, projecting 14" above ground, from which bearing trees mkd. by Markham:

A cedar, 21" diam., bears S.47 3/4°E., 20 lks., with scribe mark S visible on opened blaze.

A cedar, 11" diam., bears S.12°E., 16 lks., with scribe marks ¼ S3 visible on opened blaze

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2777, surveyed June/July 2015/- (DCSO records Vol. 58 Page 23510-11)

The ¼ sec. cor. of sec. 3 only, on the N. bdy. of the Tp., established by Quimby, in 1996, and is accepted as the cor., monumented with an iron rod, 5/8" dia. firmly set, projecting 4" above ground, with yellow plastic cap mkd. AA SURVEYING INC, from which the remains of the BTs mkd. by Quimby

A cedar, 10" dia., bears N.24¾°E., 14.1 ft., with scribe marks N¼ S3 BT visible on a partially healed blaze.

A madrone, 8" dia., bears S.83½°W., 16.0 ft., with scribe marks N¼ S3 BT visible in the bark.

A cedar, 24" dia., bears N.52¼°W., 3.3 ft., with scribe marks N¼ S3 BT visible on a partially healed blaze.

At the corner point Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, directly over the iron rod, with brass cap (properly) mkd.

Deposit the iron rod inside of the stainless steel post.

From this cor., a point erroneously established as the ¼ sec. cor. of sec. 3 only, by Markham, in 1951, bears N.72°52'39"E., 16.67 ft., and was not correctly positioned and is not utilized in the course of this survey, monumented with an iron pipe, 1¼" dia., firmly set, projecting 14" above ground, from which bearing trees mkd. by Markham, reported by Seibold and Browning in 1993-95

A cedar, 26" dia., bears S.60¾°E., 11.7 ft., with a healed blaze. (Record, S.47¾°E., 13.2 ft.)

A cedar, 14" dia., bears S.12°E., 10.6 ft., with illegible scribe marks visible on a partially healed blaze.

From this same cor., a point established as the ¼ sec. cor. of sec. 3 only, in an administrative survey by the BLM in 1978, bears S.84°07'56"E., 4.84 ft., and was not utilized in the course of this survey, monumented with an iron pipe, 1" dia., firmly set, projecting 7" above ground, from which a BT mkd. by the BLM.

continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. of Sec. 3 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A cedar, 12" dia., bears N.39¼°W., 3.2 ft., with a healed blaze.
Remove the 1978 administrative survey monument and bury alongside the stainless steel post.