

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6996)

-----  
Set post, cor. of secs. 10, 11, 14 and 15, from which  
A W.Oak 6" dia., bears S.65°W., 29 lks. dist.  
A W.oak 4" dia., bears N.40°W., 63 lks. dist.  
A W.Oak 5" dia., bears N.70°E., 80 lks. dist.  
A Red Fir 8" dia., bears S.35°E., 54 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7047-48)

-----  
The post set for this cor. is gone; the bearing trees in secs. 15, 10 and 14 are all standing. I restore this cor. by setting an Oak post, 4 ft. long, 4" sq., 24" in the ground, marked T30S S11 on NE.; R4W S14 on SE.; S15 on SW.; S10 on NW. faces, with 4 notches on S. and 2 notches on E. edges, from which  
A Fir 18" dia., bears S.31½°E., 54 lks. dist. mkd. T30S R4W S14 BT.  
An Oak 6" dia., bears S.52 3/4°W., 29 lks. dist. mkd. T30S R4W S15 BT.  
An Oak 8" dia., bears N.41½°W., 59 lks. dist. mkd. T30S R4W S10 BT.  
(These three trees are the old ones, whose marks being dim, I re-mark)  
A Fir 10" dia., bears N.49°E., 30 lks. dist. mkd. T30S R4W S11 BT.

Survey by Robert M. Thompson - Oct. 20, 1957 - C.S. File 42/236

-----  
Found - Orig. D.Fir BT, N.49°E., 30 lks., a cut stump with scribe open.  
A renewed BT, 18" D.Fir, must be S.33°E. to agree with others) 54 lks.  
A dead, rotted 5" Oak, OK, on bearing (N.70°E. 80 lks.) is actually 4.0 ft. further.  
  
A 4" W.Oak, N.40°W., 63 lks., OK.  
Other new and old BTs (5) rotted out.  
I Set a 2" x 2" x 4 ft. scribed Oak stake and scribe:  
15" D.Fir, N.75°50'E., 14.8 ft.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - June 1963 - C.S. File 53/26-59

-----  
Found - Orig. 18" now 20" R.Fir S.32°E., 35.6 ft shows scars  
Orig. 10" now 20" Fir stump, N.49°E., 19.8 ft.,  
shows good reverse scribing.  
15" R.Fir N.76°E., 14.8 ft., shows good bark  
scribing. (Thompson's BT)

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 4 W  
S 10 | S 11  
S 15 | S 14  
1963

New BT - 20" R.Fir bears S.88°W., 17.5 ft. scribed S15 T30S  
R4W CS BT.

Douglas County Surveyors Office - L. Langlitz, Deputy - L.E. Monrean; P. Earle, crew - Wit: Elmer Sutton - April 30, 1979  
- C.S. File 60/24-26

-----  
Found - Original monuments not found.  
Found 1963 DCSO brass cap.  
Orig. R.Fir, 8" dia., now a snag 22" dia. with well  
healed double blaze, bears S.35°E., 34.6 ft.  
(orig. dist. 35.6 ft., 1889 records show bearing  
S.31½°E., 35.6 ft.)  
An 1889 BT, a 10" Fir now a stump 24" dia., bears  
N.49°E., 21.0 ft. (Rec. 19.8 ft.) Stump has  
previously opened blaze with scribing visible  
"R4W", also reverse scribing "R4W" found on  
pieces of chopped out blaze laying on stump. A  
ring count shows tree growth 60 to 70 years after  
blaze and scribing.  
A D.Fir 15" now a 16" snag, bears N.73½°E., 13.9 ft.  
(Rec. N.75°50'E., 14.8 ft.) Tree bark scribed  
"S11 3683 BT".  
A 20" R.Fir now a 24" snag, bears S.84°W., 16.4 ft.  
(Rec. S.88°W., 17.5 ft.) Tree has partially  
healed pitched over blaze.

No new monument set.

New BTs -7" Madrone bears S.25°E., 22.1 ft. Tree blazed and  
scribed "T30S R4W S14 CS BT" on double blaze.

A Fir 20" dia., bears N.29°E., 35.2 ft. Bark scribed  
"T30S R4W S11" on lower blaze scribed "CS BT".

A Fir 18" dia., bears N.52°W., 78.9 ft. Tree blazed  
and scribed "T30S R4W S10 CS BT" on double blaze.

Old E-W fence bears South, 2.6 ft.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1070, surveyed June 1981/May 1982 - (DCSO records Vol. 43 Page(s) 16812-13)

-----  
(Corner report)

The Sec. cor., perpetuated and recorded by Thompson in 1957, further perpetuated and recorded by Byron in 1963, and further perpetuated and recorded by Langlitz in 1979, monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground with 1963 brass cap, from which the remains of an original bearing tree:

A Fir snag 20" dia., bears S.34¼°E., 52 lks. dist. with fragmentary scribe marks, made by Thiel, visible on opened blaze. I open this tree further to reveal scribe marks S14 BT on original blaze. (Rec. S.31½°E., 54 lks.)

and the remains of a bearing tree mkd. by Thiel:

A sawed Fir stump 24" dia., bears N.49°E., 30 lks. dist. with scribe marks 4 S and a chaining notch visible on opened blaze.

and the remains of a bearing tree mkd. by Thompson:

A Fir snag 17" dia., bears N.73°E., 19 lks. dist. with scribe marks S11 BT 3683 visible on open blaze.

and a bearing tree by Byron:

A Fir 24" dia., bears S.84°W., 25½ lks. dist., with healed blaze.

and bearing trees mkd. by Langlitz:

A Fir 21" dia., bears N.28°E., 53 lks. dist., with scribe marks T30S R4W S11 BT visible on bark blaze.

A Madrone 8" dia., bears S.25½°E., 32½ lks. dist., with scribe marks T30S R4W S14 BT visible on open blaze.

A Fir 19" dia., bears N.52½°W., 119 lks. dist., with scribe marks T30S R4W S10 bT visible on open blaze.

Latitude 42°58'08.00"N

Longitude 123°08'54.81"W

Lat & long from BLM Plat (added 6/25/2008)

From this point, United States Geological Survey triangulation station "BLAND MOUNTAIN, 1953" bears N.89°03'E., 123.92 chs. dist., monumented with a standard brass tablet, 3½" dia., firmly set in exposed bedrock, with top mkd. BLAND MTN 1953 and a triangle.