

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 2 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

F.C. Frear, Deputy Co. Surveyor - Wit: A. Wallenburg; R. Morrison - Oct/Nov. 1918 - Field book 14=45; C.S. File 7/18; Vol. 3 Pg. 29; M 1-3

Renew this corner from my own work. Government set no corner. Set in 1" x 36" Iron pipe, from which
An 8" Fir bears S.45 3/4°W., 5 lks.
A 20" Fir bears N.45°W., 15 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - May 1963 - C.S. File 52/126-143

Found - 1" Pipe at corner.
Frear BT, 8" Fir S.45 3/4°W., 5 lks. Tree has been pushed down the hill about 60 ft., found scribing.
NW BT not found.
New BTs -10" Cedar S.2°W., 14.0 ft. mkd. 1/4 S2 CS BT.
6" Cedar S.23°E., 22.6 ft. mkd. 1/4 S2 CS BT.