

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 600320

PRIMARY CORNER DESCRIPTION So. 1/16 cor. between Secs. 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1070, surveyed June 1981/May 1982 - (DCSO records Vol. 43 Page(s) 16808)

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd. S 1/16
S 23|S 24
1981

from which

A Fir 10" dia., bears S.88°E., 246 lks. dist. mkd. S 1/16 S24 BT.

A Fir 28" dia., bears S.14°W., 163 lks. dist. mkd. S 1/16 S23 BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - Feb. 10, 1994 - C.S. File 64/50-22

Found - 3¼" dia., 1981 BLM Brass cap on a 2½" O.D. iron pipe 1" below ground. BC/IP leans 4" northwest of plumb.

28" dia., now 31" dia., D.Fir with a fully healed single low blaze, bears S.14°W., 108.4' (Rec. S.14°W., 107.6' dist. possible face measurement)

10" dia., now 13" dia., D.Fir with a fully healed single low blaze, bears S.88°E., 160.8' (Rec. S.88°E., 162.4' dist. is a slope measurement)

BC/IP returned to plumb position. BC is now flush with ground.

New BTs- 7" dia., B.Oak double blazed and scribed "S1/16 S24 CS BT", bears N.74½°E., 132.2'.

16" dia., Madrone double blazed and scribed "S1/16 S23 CS BT", bears N.86¼°W., 58.0'.

(sketch in file.)