

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 601700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only, T29-4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6361)

-----  
Set ¼ sec. post at proper distance, from which  
A B.Oak 16" dia., bears S.35°E., 15 lks. dist.  
A W.Oak 12" dia., bears N.55°E., 60 lks. dist.

-----  
GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 15 Page(s) 6400) and (Vol. 17 Pages 7040-41)

-----  
¼ sec. cor. post is gone, but both bearing trees are standing. I restore this corner by setting a Cedar post, 3 ft. long, 3" sq., 24" in the ground, mkd. ¼ S on N. face, from which  
A B.Oak 24" dia., bears S.35°E., 15 lks. dist. mkd. ¼ S BT  
A W.Oak 15" dia., bears N.55°E., 60 lks. dist. mkd. ¼ S BT

-----  
F.C. Frear, Deputy Co. Surveyor - Wit: A. Wallenburg; R. Morrison - Oct/Nov. 1918 - Field book 14=45; C.S. File 7/18; Vol. 3 Pg. 29-30; M 1-3

-----  
Set 1½" x 36" I.Pipe, as per govt. BTs.

-----  
Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - May 1963 - C.S. File 52/126-134

-----  
Found - 1" I.Pipe at corner 19.8 ft. East of cor. for 2 & 1, T30-4.  
Original BTs are same BTs as for Secs. 2 and 1.  
New BT - 7" Laurel bears N.3°E., 24.9 ft. scribed ¼ S36 CSBT.

-----  
Ron Rice, Ward NW Inc. - For: Seneca Jones Timber Co. - June 2003 - M142-46

-----  
Found - 1¼" Iron pipe.  
Orig. BTs missing  
Sec. cor. common to secs. 1, 2 T30S R4W WM marked by a 1¼" bent iron pipe bears S.89°06'25"W., 19.47'.  
Set - "T" post adjacent to both pipes.

-----  
Fd. Ok by David Edwards - Jan 2005 - M 147-18