

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION C C for Secs. 25 and 36 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 14" R.Fir now a 14" DBH D.Fir snag approx. 12 ft. tall bears N.01°W., 40.8 ft. Tree has unhealed double blaze mkd. T30S R4W S25 CS BT. (Rec. S25 T30S R4W CS BT)
Monument position is accepted.
New BTs -A 6" DBH D.Fir bears S.51½°W., 31.0 ft. and is scribed "T30S R4W S36 CS BT" on a double blaze.
A 7" DBH D.Fir bears S.65°W., 61.2 ft. and is scribed "T30S R4W S36 CS BT" on a double blaze.
The 14" Fir and the new BTs are tagged with DCSO BT tags.

Cor. used in BLM Administrative survey in 1981 - See BLM for information.

David Edwards - For: Rome Creek Timber LLC - Sept. 2011 - M162-72

A BLM Administrative survey... dated 1981 by Bill May established the NE cor. of sec. 36
Set true closing cor. 1981 Admin survey BTs:
Found - 18" Fir N.69½°E., 11.9'
15" Fir N.67°W., 20.5'
Both w/healed blaze.
Set - 5/8"x30" steel rebar with 2½" dia., alum. cap as per 2009 BLM Manual & Mkd. "LS 2339" and "ROSEBURG RESOURCES COMPANY" and "2011"
6' steel post 2' west.
6' steel post 2' west.

CC BC (DCSO per BLM admin survey) bears N.89°00'42"E 54.91' with the following BTs:
18" Fir, S.51½°W., 31.0'
24" Fir S.65°W., 61.2'
Both with healed blaze.