

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 046060

PRIMARY CORNER DESCRIPTION SE Cor. N. Briggs DLC #46

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original DLC survey by Bowman and Burnett under Contract date Sept. 24, 1855

Set a post marked, from which
A B.Oak 18" dia., bears N.37½°W., 323 lks.

E. Summers - For: Bollenbaugh Estate - April 2, 1920 - Vol. 3 Page 68

Reset from old BT. Set stone from which new BTs are as follows:
A B.Oak 12" dia., bears S.16°00'E., 78 lks.
A B.Oak 18" dia., bears N.5°00'W., 16 lks.

John H. Markham, Jr. - For: Hausteader Lumber Co.- April 4, 1951 - C.S. File 40/250A-4

Determined by O.B.T.
A B.Oak snag bears N.5°E., 10.5 ft. all scribing showing.
At corner point, found stone and Set 1" x 24" I.P, from which Fir 6" dia., bears S.4°E., 24.5 ft. mkd. CL 46 BT.
A B.Oak 11" dia., bears N.13°E., 56.0 ft. mkd. CL 46 BT.

Doug. County Surveyors Office - Clell Goodwin, Deputy - Gary Langlitz; Vic Cangie; Lenora Ladig - Oct. 16, 1975 - C.S. File 57/36-18

Found - 1" x 24" O.D. I.P. laying on the ground, from which
A 10" Fir stump, was 6" Fir, with visible scribe BT" bears S.4°E., 24.4 ft.
A stump hole bears N.5°E., 10.5 ft.
An orig. 18" now 36" B.Oak showing good scar bears N.37½°W., 208.1 ft. (Call: N.37½°W., 213.2 ft.)
No sign of other tree.

At the corner as determined by record distance and bearing from O.B.T. We Set: a 1" x 30" I.P. with brass cap stamped:
Douglas Co. Surveyors T 30 S R 5 W
1975 S.E. Cor.

DLC 46

from which
An O.B.T. 36" B.Oak bears N.37½°W., 213.2 ft.
10" Fir stump bears S.3°E., 20.3 ft.
14" B.Oak scribed "SE Cor. DLC #46 CS BT" in a double blaze, bears N.29°E., 46.3 ft.
21" I.Cedar scribed "SE Cor. DLC 46 CS BT" in a double blaze bears N.71½°E., 33.2 ft.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. Brass cap as per record. R. Brown, May 1993, M 112-76 ABC

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Oct. 12, 2012 - C.S. File 67/36-33

Found - No evidence of previous monuments deep fill for base of abandoned dam project covers area.
A B.Oak 18" dia., now a 39" dia., B.Oak with a fully healed single blaze (probably previously opened); bears N.38½°W., 213.2 ft. (rec. N.37½°W., 213.2 ft) OBT
No evidence of 1920 renewal BTs fd.
No evidence of 1951 renewal BTs fd.
A 14" B.Oak now a 24" dia., 1 ft. tall Oak stump with no evidence remaining of blazing or scribing; bears N.27½°E., 46.3 ft. (rec. N.29°E., 46.3 ft.) 1975
A 21" I.Cedar now a 32" dia., 4½ ft tall, I.Cedar stump with no blazes evident (due to thick furrowed bark); bears N.75½°E., 33.2 ft. (rec N.71½°E., 33.2 ft.) 1975

New - At a point determined by intersecting the record dist. measurements from the three fd. BTs. We set a 2⅜" dia., brass cap on a 32" long 1" ID iron pipe 30" in the ground. (BC mkd)

COUNTY SURVEYORS OFFICE
T30S
SE
DLC 46
R5W
2012

A 19" dia., D.Fir scribed "SE DLC 46 CS" "BT" on a double blaze; bears N.61½°E., 71.5 ft.
A 10" dia., Maple scribed "SE DLC 46 CS" "BT" on a double blaze; bears S.65°W., 120.3 ft.
A double trunk I.Cedar, the 14" dia., SE trunk of which is scribed "SE DLC 46 CS" "BT" on a double blaze; bears N.14¾°W., 61.8 ft. (to CRC of double trunk)

Note - Monument is on moderate SE slope on North side wide Canyon running NE'ly. Monument just above a flat bench in and near the north perimeter of the fill base of an abandoned dam project.
Compass decl. 15½°E.