

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 063050

PRIMARY CORNER DESCRIPTION E NE Cor. Tiller DLC #63

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original DLC survey by Bowman and Burnett, under Contract date Sept. 1855

Set a post marked, from which
A B.Oak 18" dia., bears S.59°W., 44 lks.
A B.Oak 10" dia., bears N.76°W., 62 lks.

Herbert Northcraft - For: Wesley Larson - May/June 1972 - M 46-9

Found - Rock at fence corner.
24" Y.Oak S.51°W., 23 ft.
New BT - 18" B.Oak N.70°W., 34 ft. "NE Cor. DLC" #750
(Same point used by E. Woodford in 1946)

Doug. County Surveyors Office - L.E. Monrean; P. Earle; K. Cheney - Aug. 26, 1976 - C.S. File 59/18-25

Found - A stone, (conglomerate) 7" x 5" X 8" above ground, firmly set at old fence corner. Stone tied as DLC corner by Northcraft in 1972.
An 18" Oak now 24" stump, Y near base. Stump bears S.59°W., 29.0 ft. Tree has possible blaze, rotted, no scribing found.
A B.Oak 10" now 20", bears N.76°W., 40.9 ft. Tree scribed "NE Cor DLC BT" by Northcraft as BT to stone. I open tree (this destroys Northcraft scribing). At approx. 110 growth rings, I find old face with scribing "S30 BT" on double blaze.
Set Brass cap at intersection of orig. BT calls, stamped:
County Surveyors Office:

T 30 S	R 5 W
ENE	
Cor DLC #63	
1976	

New BT - 6" W.Oak bears S.59°W., 52.8 ft. Tree double blazed and scribed "DLC 63 CS BT"
Stone bears S.82°W., 7.6 ft.

Fd. Ok, Dec. 1996, K. DeGroot, M 126-29

DCSO-GIS Corner visitation - 1/13/2005 - Typed: 2/2/2011 - C.S. File 67/33-1

Monument - BC/IP - 1¼" IP w/BC
Comment - OK