



TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 100242

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 25 only, T. 30-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A 1969 DCSO 1 1/4" I.P. (1/4 Cor. Sec. 30, T30-5 only) bears South, 99.4 ft. (A new DCSO BC/IP is now at position of found 1 1/4" I.P.)  
Previously described 1 1/4" O.D. I.P. is referenced to plumb position and removed, I.P. measures 36" long.  
Set a new DCSO 2 3/8" dia. Brass cap on a 30 1/2" long 1 1/4" O.D. Iron pipe, protrudes 1 ft. above ground, set at referenced position. Cap is mkd: "Douglas County Surveyor T30S 1/4 S25 R6W R5W 1989 Office".  
New Accessory:  
A white metal witness post is set 1 ft. North of brass cap/iron pipe.  
Corner lies in open field.

---

DCSO-GIS Corner visitation - 1/3/2005 - Typed: 2/7/2011 - C.S. File 67/33-1  
-----  
Monument - 1 1/4" IP  
Comment - ok

---

Carl Sweeden - For: Mike Swett - March 2015 - M169-11  
-----  
Found - 2 1/2" DCSO BC "1989" UP 1.0'  
16" W.Oak BT, S.24°W., 127.4', SCAR VIS., TAG  
20" W.Oak BT, S.80°W., 262.6', HEALED, TAG

---

2