

PRIMARY CORNER DESCRIPTION Sec. Cor. for 6 & 7 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7129)

-----  
Set a post corner of secs. 1, 6, 7 and 12, from which  
A B.Oak 12" dia., bears S.45°W., 327 lks. dist.  
A B.Oak 12" dia., bears S.35°E., 203 lks. dist.  
A B.Oak 4" dia., bears N.30°W., 394 lks. dist.  
A Maple 3" dia., bears N.27°E., 39 lks. dist.

M. B. Germond - Wit: F.C. Frear; Hank Weaver - May 1917  
F.B. 42 Pg. 53; Vol. 3 Pg. 42; C.S. File 7/9; and M 1-35, and  
"old" cor. book, Page 145)

-----  
I reset this corner from one old original bearing tree which I find plainly marked. The new corner is a 1" x 30" Iron bolt and 12" x 18" stone, from which  
A W.Oak 14" dia., bears S.39°10'W., 4.07 chs.  
A W.Oak 12" dia., bears S.10°00'E., 3.64 chs.  
A B.Oak 10" dia., bears N.61°45'W., 3.25 chs.  
A B.Oak 24" dia., bears N.30°00'W., 3.94 chs. (old BT)

Ben B. Irving, D.C.S. - Wit: L.H. Smick; N.E. Richardson - April 1929 - M 1-61; C.S. File 1/65 A & B and "old" cor. book, Page 183.

-----  
Set from Frear's BTs. I. Bolt and stone gone. Drove 1" x 36" Pipe, 26" in underground.

Doug. County Surveyors Office - James W. Bryon, Deputy - Mike Darby; Jim Halterman - Oct. 1963 - C.S. File 53/26-24

-----  
Found - 1" I.Bolt, 12" under surface.  
20" W.Oak S.39°W., 268.6 ft. shows good scar.  
20" B.Oak N.62°W., 314.5 ft. shows good scar.  
16" B.Oak S.10°E., 240.2 ft. shows good scribing.  
New BT - 11" B.Oak bears S.29°E., 213.7 ft. scribed S7 T30S  
R5W CS BT.

Doug. County Surveyors Office - L.E. Monrean, Deputy - K. Reed; P. Earle; T. Plouff - Oct. 2 & 4, 1979 - C.S. 60/34-17

-----  
Found - No original post found. No stone found. No pipe Fd.  
A 1" x 30" I.Bolt buried 8" below surface.  
A 20" W.Oak now 22" with well healed single blaze,  
bears S.39°W., 268.6 ft.

(Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 6 & 7 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A 20" B.Oak now 22 with well healed double blaze bears N.62°W., 215.8 ft. to center, 214.5 ft. to face. (Byron 1963 visit is in error for this distance)  
A 16" B.Oak now 18" with previously opened blaze showing visible scribe "S7 T30 5" bears S.10°E., 241.2 ft. to center, 240.2 ft. to face.  
An 11" B.Oak now an 18" in dia., 2.0 ft. high stump bears S.29°E., 213.7 ft.  
Set a 1" x 36" I.P. with brass cap stamped "Douglas County Surveyor" T30S R6W S12 S6 S7 R5W 1979" at corner position 14" below surface of ground. Set I. Bolt along northerly edge of cap 2" lower.  
No new accessories. Cor. lies in large plowed field.

Doug. County Surveyors Office - Randall Smith; Steve Flause  
June 8, 1984 - C.S. File 62/18-25  
-----  
CORNER REPORT ONLY  
Monument not looked for. Corner lies in wheat field.  
Found - 11" now a 18" dia., 2 ft. high B.Oak stump.  
20" now a 22" W.Oak with well healed blaze.  
12" now a 18" B.Oak with previously opened blaze showing visible scribing "S7 T30 5".  
10" B.Oak is probably there, found a tree showing faint scar and diameter size of NW tree found per 1979 Co. visit. Tree is along fence line and has fencing attached to trunk.

Cor. Fd. and Used in BLM resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1551, Surveyed Aug. 1990/July 1991 (DCSO Records, Vol. 50 Page 19200)