

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 174100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 only T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W. P. Wright, under Contract #281 dated May 16, 1878 (DCSO records, Vol. 19 Page 7887)

Can find no evidence of survey. Am informed by the County Surveyor and others that they have never been able to find one. The ¼ sec. post bet. secs. 31 and 32, (T30-5), I could not find to my satisfaction.
I set a post for closing corner. A post 5x5 ins. diam., 4 ft. long in mound or rock. No witness trees for cor. to secs. 5 and 6.

Arthur R. Evans, Professional Engineer - For: Pacific Lumber Distributors - Feb/March 1955 - C.S. File 41/367-1; M 12-15

This corner was set by a projection of the line between the cor. of secs. 5, 6, 7 & 8 and the ¼ cor. of secs. 5 & 6, T31S R5W, and its intersection with the Tps. line between T30S R5W and T31S R5W as established by Dep. Co. Surveyor (CS 44/151) Set 3/4" Iron Rod.
Blazed and scribed 2 BTs:
17" D.Fir S.59½°W., 60.0 ft. mkd. T31S R5W S6 BT. Copper tag R.E. 2741.
20" D.Fir S.48°E., 54.8 ft. mkd. T31S R5W S5 BT R.E. 2741.
(Distances to center of trees.)

Fd. OK, DCSO, L. Monrean, Jan. 30, 1979, C.S. File 61/3

Ron Quimby - For: Cow Creek Indians 6/2016 - M171-12 A&B

Found - ¾" iron rod per M12-15
20" D.Fir S.59½°W., 60.0' no uprooted snag.
32" D.Fir S.48°E., 54.8' with good scar.
New - 12" D.Fir S.54°W., 10.9' scribed "T31S R5W S6 BT"
11" D.Fir S.32°E., 19.6' scribed "T31S R5W S5 BT"
30" D.Fir S.81°W., 30.8' scribed "T31S R5W S6 BT"