

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7147)

Set ¼ sec. post, from which
A Laurel 12" dia., bears N.25°W., 42 lks.
A Laurel 8" dia., bears S.10°E., 29 lks.

1/4 Corner used in GLO survey by W.P. Wright under Contract #281 dated May 16, 1878 (DCSO records, Vol. 19 Page 7889)

A. Boyer - Wit: Ted Ross; Geo Bollenbaugh - March 9, 1939 - C.S. File 16/19 and "old" Cor. Bk. Pg. 176

Found stumps of BTs, both trees were cut off high and the tree to the NW shows the blazes for scribing, but is rotten in the heart. Someone drove a 3/4" pipe in center of rock pile where corner is. (This is possibly from Field Book #10)
Marked two new trees:
A 12" Fir N.29½°E., 42 ft. mkd. ¼ S33 CS BT.
A 4" laurel S.50°W., 18 ft. mkd. ¼ S32 CS BT.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam - For: C & D Lumber Co. - July 23, 1959 - C.S. File 49/168; M 15-33

Found - 1" Pipe.
8" Laurel S.50°W., 18 ft. scribing all visible, "¼ S32 CS BT".
Stump of Fir N.29½°E., 42 ft. showing traces of scribing.
Remnants of Laurel stumps N.25°W., 27.7 ft. and S.10°E., 19.1 ft. No scribing found. Stumps too far gone.
Blazed and scribed new BT:
8" B.Oak S.54½°E., 31.4 ft. scribed ¼ S33 CS BT.
Corner lies in fence corner - fence runs North and West.

Doug. County Surveyors Office - Gary Langlitz, Deputy - Karen Reed; Frank Silagy; Vicki Woodral; Stephen Flause; Ed Monrean July 5, 1979 - C.S. File 61/3

Found - 1" I.P., 1.2 ft. above ground.
12" Laurel now an undetermined dia. rotted tree remnants in hole bears N.25°W., 27.7 ft. (Orig.)
8" Laurel now a roothole bears S.10°E. 19.1 ft (OBT)
12" Fir now a 20" rotted stump with scribe "CS BT" visible bears N.29½°E., 42.0 ft. Upper portion of tree has illegible scribe marks. (Cont. Next Pg)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>4" Laurel now a 12" bears S.50°W., 18 ft. to face, 18.7 ft. to center dist. with visible partial scribing.</p> <p>8" B.Oak now an 11" bears S.54½°E., 31.4 ft. with well healed double blaze.</p> <p>Replaced 1" I.P. with a 1" x 36" I.P. with brass cap mkd: "Douglas County Surveyor" T30S R5W ¼ S32 S33 1979. Place 1" I.P. along west side.</p> <p>New BTs -9" Fir bears N.46°E., 41.6 ft. scribed "¼ S33 CSBT".</p> <p>15" Fir scribed "¼ S32 CS BT" bears N.43½°W., 40.3 ft. with double blaze.</p> <p>9" Fir scribed "¼ S32 CS BT" in a double blaze bears S.36°W., 31.5 ft.</p> <p>Fence corner fence runs North and West.</p>
<p>Fd. OK, August 1991, R. Brown, M 113-68</p> <p>Fd. Ok, Dec. 1992, R. Brown, M 117-57</p> <p>Fd. OK, Nov. 1993, R. Brown, M 119-12</p> <p>Fd. Ok by DCSO - R.W. Smith, 3/6/2001 - C.S. File 66/21-2</p> <p>Fd. OK, Jan. 2002 by R. Brown - M139-48</p> <p>Fd. OK by R. Brown, April 2002 - 2002-0023</p> <p>Fd. Ok by R. Brown, Aug. 2009 - M157-16</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Jan. 31, 2013 - C.S. File 67/38-14</p> <p>-----</p> <p>Found - 1979 DCSO 2½ dia., BC (properly mkd) on a 1" ID iron pipe, firmly & plumbly set, protruding 3" above ground.</p> <p>3/4" IP is set on the west edge of the fd BC monument protruding 3" above ground. 1939</p> <p>A very large irregular root-hole with a small live madrone trunk growing from remaining fragment of old Madrone trunk. The near center of this root-hole bears N.25°W., 27.7 ft. (as per rec.) OBT?</p> <p>A 12" fir, now a rotted to ground and broken apart, D.Fir stump with parts of healed blaze edges nearby; bears N.29½°E., 42.0 ft (as per rec) 1939</p> <p>A 4" laurel now a dead but still intact 15" dia, madrone with a partially healed single blaze, scribing no longer visible; bears S.54°W., 18.7 ft. (rec. S.50°W., 18.7 ft.) 1939</p> <p>An 8" B.Oak now a dead and fallen (partially cut up) 13" dia., B.Oak with a fully healed double blaze; the root-hole of which bears S.54½°E., 31.4 ft. (as per rec.) 1959</p>
<p>continued next page</p>

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

	<p>A 9" fir now a 14" dia., 7½ ft. tall D.Fir stump with a fully healed double blaze; bears N.46°E., 41.6 ft. (as per rec.) 1979</p> <p>A 15" fir now a 24" dia., 4 ft. tall D.Fir stump with a fully healed double blaze; bears N.43½°W., 40.3 ft. (as per rec.) 1979</p> <p>A 9" fir now a tall dead 17" dia., D.Fir with a fully healed double blaze; bears S.37¼°W., 31.5 ft. (rec. S.36°W., 31.5 ft.) 1979</p> <p>New - A 10" dia., Maple scribed "¼ S33 CS" "BT" on a double blaze; bears N.21¼°E., 32.4 ft.</p> <p>A crooked trunked 6" dia., D.Fir scribed "X" "CSBT" on a high-low blaze; bears S.64½°E., 14.9 ft.</p> <p>A 14" dia., Madrone scribed "¼ S32 CS" "BT" on a double blaze; bears S.55½°W., 21.3 ft.</p> <p>A 7" dia., D.Fir scribed "¼ S32 CS" "BT" on a double blaze; bears N.53½°W., 20.8 ft.</p> <p>Note - Monument is at bottom of NE'ly slope in a sparse woodland of oak, fir, maple & madrone. A corner fence post of a mostly fallen fence running west lies approx. 1 ft. North of BC monument.</p> <p>Compass decl. 15½°E.</p>
	<p>Raymond Brown - For: Cow Creek Band of Umpqua Tribe of Indians - 10/2013 - M166-4</p> <p>-----</p> <p>Fd. Brass cap. N = 469163.745 E = 4169836.518 State Plane Coordinates NAD 83 South Zone</p>
	<p>Fd by R. Brown 3/2015 - 2015-0022 Fd by R. Brown 7/2016 - M172-43 Fd. By R. Quimby 10/2018 - M175-1</p>