

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Pages 7172-73)

Set a Fir post 3 ft. long, 3" sq. 24" in the ground for ¼ sec., mkd. ¼ S on W. face, from which

A Fir 12" dia., bears N.42½°W., 20 lks. mkd. ¼ S BT.

A B.Oak 7" dia., bears N.39½°E., 18 lks. mkd. ¼ S BT.

John H. Markham, Jr. Engineer, April 4, 1951 - For: Hausteader Lbr. Co. - C.S. File 40/250A-5

A Fir 20" dia., bears N.42°30'W., 13.2 ft. I rescribe this O.B.T.

A B.Oak windfall bears N.39°30'E., 12.0 ft. scribe showing. At corner point, Set 1" x 24" Iron pipe from which

A Fir 14" dia., bears S.47°E., 5.0 ft. mkd. ¼ S2 T30S R5W 2880 BT.

Doug. County Surveyors Office - James W. Byron, Deputy - Sept. 1963 - C.S. File 53/26-7

Found - I.Pipe at corner and both BTs as recorded by Markham in 1951. SE BT, now dead.

New BT - 14" Fir N.3°E., 9.0 ft. scribed ¼ S2 CS BT.

BLM resurvey by Lynn Roseberry & James Jelley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO records, Vol. 38 Pages 15533-34)

The ¼ sec. cor. perpetuated and recorded by Markham, 1951, subsequently perpetuated and recorded by Byron in 1963, monumented with an iron pipe, 1" dia., firmly set, projecting 4" above ground, from which the remains of the original bearing trees:

A Fir 27" dia., bears N.42½°W., 20 lks. dist., with healed blaze and scribe marks ¼ S3 visible on bark blaze.

This tree was rescribed by Markham.

and the remains of a bearing tree mkd. by Markham:

A Fir snag 16" dia., bears S.46 ¾°E., 9 lks. dist., with scribe marks ¼ S T30S R5W 2880 visible on partially healed blaze.

and a bearing tree mkd. by Byron:

A Fir 17" dia., bears N.3°E., 14 lks. dist., with scribe marks BT visible on partially healed blaze.

At the Corner Point

(Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over the iron pipe, with brass cap mkd:
T 30 S R 5 W
¼
S 3 | S 2
1969

Fd. & used by BLM resurvey by Wayne L. Rogers, under Group # 1565, surveyed Aug. 1990/July 1991 (DCSO Records Vol. 50 Page(s) 19114-15)

Fd. OK by W. Rogers, April 2000 - M134-52

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2812, surveyed Sept. 2015 - (DCSO records Vol. 58 Page 23490 & Plat T30-5 2017-1)

The ¼ sec. cor. of secs. 2 and 3, monumented with an iron post, 2½" dia., firmly set, projecting 5" above ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree
A fir, 35" dia., bears N.42½°W., 13.2 ft., with a healed blaze.
and the remains of a bearing tree mkd. by Markham, Jr., in 1951, reported by Roseberry and Jelley in 1967-69
A hollowed, decayed fir stump, 18" dia., bears S.46¾°E., 5.9 ft., with a hollowed blaze.
and the bearing tree mkd. by Byron, in 1963, reported by Roseberry and Jelley in 1967-69
A fir, 23" dia., bears N.3°E., 9.2 ft., with a healed double blaze.

NAD 1983 (2011)
Latitude 42°59'25.93"N. Longitude 123°15'57.32"W.