

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 534700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 35 only, T29-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6423)

Set ¼ sec. post at proper distance, from which
A B. Oak, 10" dia., bears N.37°E., 43 lks.
A B. Oak, 12" dia., bears S.75°W., 84 lks.

G.L.O. Survey by Oscar F. Thiel, under Contract #658 dated May 21, 1896. (DCSO Records Vol. 17 Page 7182)

CORNER REPORT ONLY

The fire, that appears to have raged here about 8 years ago, has destroyed all the timber and the ¼ sec. cor with its witness trees.

Doug. County Surveyors Office - James W. Byron, Co. Surveyor - John M. Powell & Crew - April, 1969 - C.S. File 54/84 - M 37-44.

This corner set from survey at pro-rated distance.

Set - Brass Cap at Cor. mkd:

County Surveyor's Office
1969
T 29 S R 5 W
¼ S 35

New BTs -13" D. Fir, N.4½°E., 46.8' mkd: "¼ S35 CS BT"

10" Laurel, N.58°E., 22.3' mkd: "¼ S35 CS BT"

This corner lies north 4.0' of east-west fence line.

B.L.M. Resurvey By Lynn M. Roseberry & James E. Jelley, under Group #662. Surveyed Oct. 1967/June 1969. (DCSO records Vol. 38 Page 15515)

The ¼ sec. cor. of sec. 35 only, re-established by James W. Byron, Deputy Co. Surveyor, in 1969, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap mkd:

County Surveyors Office

T 29 S R

¼ S 35 5

T 30 S W

from which the remains of bearing trees mkd. by Byron

A fir stump, 13" dia., bears N.3¾°E., 71 lks., with scribe marks ¼ S35 CS BT visible on open double blaze.

A madrone, 10" dia., bears N.57¼°E., 34½ lks., with scribe marks ¼ S35 CS BT visible on double blaze.

FD. BC J. Markham, 3/1978 - C.S. File 58/168-2

Cont.

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 534700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 35 only, T29-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2795, surveyed July/Aug. 2015- (DCSO records Vol. 59 Page 23572-3)

The ¼ sec. cor. of sec. 35 only, on the S. bdy of the Tp., monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground, with brass cap (properly) mkd. Note: There is no remaining evidence of bearing trees mkd. by Byron, County Surveyor, in 1969, as reported by Roseberry and Jelley in 1967-69.

from which new bearing trees

An oak, 9" dia., bears N.1½°E., 41.4 ft., mkd. X BT.

An oak, 10" dia., bears N.55½°W., 28.6 ft., mkd. ¼ S35 BT.

From the corner

S.70°W., 5.9 ft. to the cor. of fence lines extending N., E. and W.