

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7137)

Set a post cor. of secs. 13, 14, 23 and 24, from which
A Pine 10" dia., bears S.35°E., 80 lks. dist.
A B.Oak 15" dia., bears N.45°E., 20 lks. dist.
A B.Oak 22" dia., bears N.10°W., 62 lks. dist.
A B.Oak 20" dia., bears S.25°W., 10 lks. dist.

F.C. Frear, Deputy - Lon Hawkins - For: J.W. Hanks - Feb. 18, 1918 - Vol. 3 Pg. 46; Field Book 43 Pg. 56 and "old" Cor. Bk. Page 146

Renew from old BTs. set in a ½" x 2" x 16" Iron bar, from which
All old original BTs bear as given and all plainly re-marked.

Doug. County Surveyors Office - James Byron, Deputy - M. Godfrey; S.A. Bilow - Aug. 1958 - C.S. File 49/107-1

Found - Orig. 20" now 24" B.Oak snag, S.25°W., 6.6 ft. Open and find good scribing "W 5"
Orig. 15" now 24" B.Oak snag N.45°E., 18.2 ft. (Rec. 13.2 ft. shows good scribing "S 3".
B.Oak now 24" that checks record distance and bearing for orig. NW BT, but I do not find scribing.
I do not find iron Bar set by Frear.
Fence corner bears S.58°W., 4.0 ft.
Set brass cap at cor. mkd: County Surveyor's S14|S13
Office, 1958 S23|S24 30S R5W
New BTs -21" R.Fir bears S.80°E., 26.8 ft. scribed S24 T30S R5W CS BT.
12" Cedar bears N.62°E., 52.3 ft. scribed S13 T30S R5W CS BT.
7" R.Fir bears N.16°W., 31.2 ft. scribed S14 CS BT.
14" Cedar bears S.18°W., 66.3 ft. scribed S23 T30S R5W CS BT.

Doug. County Surveyors Office - James W. Byron, Deputy - Mike Darby - Sept. 1963 - C.S. File 53/26-11

Found - Brass cap at cor. and all BTs as recorded, except SE BT, now down.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

	<p>Iron bar, flush, set by Frear, 1918, bears N.45°E., 2.0 ft. from brass cap, which is 4 ft. North of fence line and 15 ft. East of centerline old logging road.</p> <p>New BT - 12" laurel bears S.22°E., 47.3 ft. scribed S24 T30S R5W CS BT.</p>
	<p>Fd. OK, Feb. 1987, Wm. Ruppert, M 103-50 Fd. Ok, Oct. 1993, R. Brown, M 119-4</p>
	<p>Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 3/2/2004 - C.S. File 67/6-8</p> <p>-----</p> <p>Found - 2½" dia., brass cap, properly marked. (1958 Byron) 1" I.D. iron pipe firmly set & protruding 10" above ground. BC monument is ~ 6 ft. north of fence line running west & SE. Also fd. ½"x2" iron bar firmly set ~ 3" below ground Bar leans ~ 4" E'ly from plumb. Plumb position bears N.35°E., 2.0 ft. from the fd. brass cap. 1963 renewal rec. N.45°E., 2.0 ft. 1918 Frear.</p> <p>All accessory bearings & distances from fd. BC. Orig. 20" dia., B.Oak now rotted to ground, Oak stump fragments bears ~ S.25°W., 6+ ft. No evidence of other orig. BTs found. From 1958 Byron ren., evidence of fallen mostly buried 20+ inch dia., D.Fir moved by cat work out of orig. position but near the call for a SE BT. No other 1958 BTs fd. From 1963 ren., the one new BT is fd: A 12" Laurel, now a 17" DBH Madrone with a fully healed double blaze bears S.22°E., 46.3 ft., dist. (rec. S.22°E., 47.3 ft., this is a slope dist.)</p> <p>New - (Measured from fd. BC position) 7" DBH Madrone scribed T30S R5W S24 CS BT on a double blaze bears S.50°E., 6.0 ft. 9" DBH Madrone scribed T30S R5W S24 CS BT on a double blaze bears S.82½°E., 17.2 ft. 8" DBH I.Cedar scribed T30S R5W S14 CS BT on a double blaze bears N.43½°W., 54.0 ft.</p> <p>Note - Monument is on gentle SE facing slope in tree line on Northerly edge of large pasture.</p>
	<p>Fd. Ok by R. Brown 4/2007 - M152-68 Fd. Ok by Raymond Brown, 12/2009 - M157-20 Fd. per record, D Edwards, 10/2023 2023-0041 Fd. as per rec 3/2024, D Edwards M183-42 Set steel post North 2' on line. _____</p>