

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Page 7167)

-----  
Set a Laurel post 3 ft. long, 3" sq. 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on N. face, from which  
A B.Oak 16" dia., bears S.49°E., 17 lks. mkd. 1/4 S BT.  
A B.Oak 10" dia., bears N.81 1/2°E., 36 lks. mkd. 1/4 S BT.

Doug. County Surveyors Office - A. R. Evans, Deputy - July/Aug 1951 - C.S. File 45/69

-----  
Set a 5/8" Iron rod from 10" B.Oak BT.  
Blazed and scribed new BTs:  
30" Fir N.8°W., 39.0 ft. mkd. 1/4 S 1 CS BT.  
20" Fir S.70°E., 56.3 ft. mkd. 1/4 S12 CS BT.

Doug. County Surveyors Office - James Byron, Deputy - Mike Darby - Sept. 1963 - C.S. File 53/26-5

-----  
Found - 5/8" Iron rod at corner.  
Find N. 16" B.Oak used by Evans to set corner, now center rotted out.  
30" Fir N.12°E., 39.0 ft. now N.8°W., shows good bark scribing.  
No trace of original SE bearing tree.  
New BT - 8" R.Fir bears S.34°W., 21.0 ft. scribed 1/4 S12 CS BT  
Corner is 50 ft. North of East-West ridge.

BLM resurvey by Lynn Roseberry & James Jelley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO records, Vol. 38 Pages 15521-22)

-----  
The 1/4 sec. cor. perpetuated and recorded by Evans, 1951, and subsequently perpetuated and recorded by Byron, 1963, monumented with an iron rod 5/8" dia., firmly set, projecting 5" above ground, from which the remains of the original bearing tree:

An Oak 16" dia., bears N.81 1/2°E., 36 lks. with opened and decayed blaze.  
and the remains of bearing trees mkd. by Evans  
A Fir 30" dia., bears N.12°E., 59 lks. dist. with scribe marks 1/4 S1 CS BT visible on bark blaze.  
A root hole bears S.70°E., 85 1/2 lks. dist., with a down Fir alongside, 20" dia., with scribe marks 1/4 S12 CS BT visible on bark blaze.  
and a bearing tree by Byron:  
(Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Fir 9" dia., bears S.34°W., 32½ lks. dist., with healed double blaze.

At the Corner Point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over the iron rod, with brass cap mkd:

T 30 S R 5 W

¼  $\frac{S 1}{S 12}$

1969

DCSO-GIS Corner visitation - 7/6/2005 - Typed: 2/8/2011 -  
C.S. File 67/33-1

-----  
Monument - 3" BC

Comment - (needs) rehab