

PRIMARY CORNER DESCRIPTION ¼ Cor. Secs. 31 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7219)

Quarter cor. coming in bluff, no post was established.

Greg Lang - For: Roseburg Resources - 5/16/2006 - M150-53 & C.S. File 65/58-17A

Set - 5/8" x 24" iron rod with aluminum Roseburg Resources cap. Iron rod was shorter than 36" standard clue to shallow rock.

- 21" D.Fir bears N.17°E., 60.00 ft scribed "¼ S32 BT.
- 26½" D.Fir bears N.27°W., 18.60 ft scribed "¼ S31 BT"
- 22½" D.Fir bears S.79°W., 7.40 ft scribed "¼ S31 BT"
- 22" D.Fir bears S.29½°E., 18.70 ft scribed "¼ S32 BT"

NOTE- We set spikes in the base of all BTs for measuring distances to the corner; bearings to the trees were measured with a total station & are based on the original survey line between the Section corners. Corner lies on a northerly slope below a very large rock. It is approx. 200' South of Cow Creek.

BLM resurvey by Joel R Herzberg, Cadastral Surveyor under Group No. 2928 - surveyed July /Aug. 2018 - (DCSO records Vol. 59 Page(s) 23665-6

The ¼ sec. cor. of secs. 31 and 32, established at mid-point between the sec. cors. by Lang, in 2006; and is accepted as a careful and faithful determination of the position of the original cor. which was not monumented in the original survey, as documented in a report by Herzberg dated August 8, 2018; monumented with an iron rod, 5/8" dia., firmly set, projecting 10" above the ground, in a collar of stone, with aluminum cap mkd.

ROSEBURG RESOURCES
T 30 S R 6 W
¼ S31 | S32
2006
LS2295
COMPANY

- from which bearing trees mkd. by Lang
- A fir, 23" dia., bears N.16¾°E., 60.1 ft., with a healed blaze, with a mag nail right side center.
- A fir, 25" dia., bears S.29°E., 17.7 ft., with a healed blaze, with a mag nail left side center.
- A fir stump, 26" dia., bears S.78¾°W., 7.4 ft., with illegible scribe marks visible on partially healed blaze, with a mag nail left side center.

Continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION ¼ Cor. Secs. 31 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir stump, 30" dia., bears N.26½°W., 19.0 ft., with scribe marks ¼ S3 visible on partially healed blaze, with a mag nail right side center.

A steel fence post is alongside the cor.

Note: The original Witness Post for the 1/4 sec. cor. of secs. 31 and 32 established by Flint, in 1855, at 5.65 chains to the north of the cor. was not recovered by any subsequent local surveys on file and was searched for but not recovered during the course of this survey.

From this cor., a point established on the line bet. secs. 31 and 32 by McLind, in 1973, bears N.0°09'56"W., 193.25 ft.; monumented with an iron rod, 5/8" dia., firmly set, projecting 2" above the ground, no cap, and a metal fence post alongside.

From this same cor., a point established at the intersection of the line bet. secs. 31 and 32 with the southerly right-of-way of the Railroad by Dolan, in 1988, bears N.0°13'32"W., 463.36 ft.; monumented with an iron rod, 5/8" dia., firmly set, projecting 4" above the ground with a yellow plastic cap mkd. LS 1076, and a metal fence post alongside.