

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 5 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6460)

Set ¼ sec. post at proper distance, from which
A B.Oak 6" dia., bears N.65°W., 84 lks.
A W.Oak 6" dia., bears S.75°W., 34 lks.

Original - Fred Mensch under Contract #757 dated Sept. 14, 1904 (DCSO records, Vol. 15 Page 6510)

The ¼ sec. cor. bet. secs. 5 and 32, on the So. bdy. of T29SR6W being partially obliterated, I reestablish this corner in its original position, as follows:
Set a slate stone 14x10x6 ins. 9½ ins. in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which
A W.Oak 6" dia., bears N.46°W., 13 lks. mkd. ¼ S32 BT.
A W.Oak 9" dia., bears S.40°W., 42 lks. mkd. ¼ S5 BT.

L.G. Hicks - For: Rice Bros. - May 1916 - C.S. File 19/28 - M 13-72

Stone at ¼ corner
6" B.Oak N.65°W., 55.4'
6" W.Oak S.75°W., 22.4'

John H. Markham, Jr. - For: Stomar Lbr. Co. - Aug/Sept. 1956
C.S. File 42/191-6

Point determined by O.B.T's
8" dead Oak N.66°W., 46.0 ft. (See Hicks Survey M 13-72)
6" dead Oak S.69°W., 21.2 ft. (See Hicks Survey M 13-72)
6" dead Oak S.42°W., 26.4 ft., found scribe. (1904)
At corner point found stone and Set a ¾" x 30" Iron pipe, from which
12" Fir bears S.36°W., 24.7 ft. mkd. ¼ S5 BT.
18" Cedar bears S.53°E., 31.5 ft. mkd. ¼ S5 BT.
Dry Creek bears East, 100 ft.
South 1/4 Cor. S. 32 bears East, 635.5 ft.
Corner lies along E-W fence.

BLM resurvey by Thielsen and White under Group #'s 348 and 350 - Surveyed July 1958/August 1959 (DCSO records, Vol. 30 Page 12812)

The 1/4 Sec. cor. monumented with a slate stone 14x10x6 ins., set in a small mound of stone, mkd. ¼ on N. face, from which the remains of trees mkd. by Mensch in 1904:
(Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 5 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An Oak 9" dia., dead and fallen, bears S.40°W., 42 lks. dist., mkd. ¼ S on open blaze.

An Oak, dead, fallen and rotted, bears N.46°W., 13 lks. dist., no marks remain.

At the Corner Point

Set an iron post, 28 ins. long, 2½ ins. diam., 3 ins. in the ground, to solid rock, and in a mound of stone, 5 ft. base, to top, with brass cap mkd:

¼ S 5
T 30 S R 6 W
1958

from which new bearing trees:

A Cedar 15" dia., bears S.51½°E., 50 lks., mkd. ¼ S5 BT.

A Fir 12" dia., bears S.31°W., 37 lks., mkd. ¼ S5 BT.

Bury original stone alongside the iron post.

BLM resurvey by Jelley and Rogers, under Group #'s 1024 and 1039 (Surveyed April/Oct. 1980 (DCSO records, Vol. 42 Pages 16564-65)

The ¼ sec. cor., monumented with an iron post, 2½ dia., firmly set, projecting 8" above ground with 1958 brass cap. from which the remains of bearing trees mkd. by Thielsen and White:

A Cedar snag 18" dia., bears S.51½°E., 50 lks. dist., with scribe marks 1/4 S5 BT visible on open blaze.

A Fir 16" dia., bears S.31°W., 37 lks., with healed blaze. and a new bearing tree

A Fir 6" dia., bears S.7 3/4°E., 154 lks., mkd. 1/4 S5 BT.

Fd. OK, Wayne Rogers, BLM survey, 1980, DCSO records, Vol. 45 Page 17260)

DCSO-GIS Corner visitation - 8/11/2004 - Typed: 2/9/2011 - C.S. File 67/33-1

Monument - 2.5" IP/BC
Comment - (needs) rehab

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 3/8/2011 - C.S. File 67/33-22

Found - A 3¾" dia., (1958) brass cap (properly mkd) on a 2½" O.D. iron pipe firmly set & protruding 8" above ground but not showing any evidence of 5 ft. mound of stone. Also no evidence of 1956 3/4" iron pipe is found.

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 5 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A loose stone measuring 5x8x12" with no marks bears S.10°W., 1.0 ft. from found BC.
No orig. 1854 BTs were found.
A W.Oak 9" dia., now a fallen and very rotted 6" dia., 6 ft. long W.Oak with no marks or scribing the center of root crown (CRC) of which bears S.40°W., 27.7 ft. (as per record) 1904
A 12" Fir now a 26" DBH D.Fir with a high fully healed double blaze; bears S.31°W., 24.4 ft. (agrees w/1958 & 1980 rec) 1956
An 18" cedar now a fallen 19" dia., 35 ft. I.Cedar snag with a partially healed double blaze showing the scribing "¼ S5" "BT" the CRC of which bears S.31°W., 33.0 ft. (agrees w/1958 & 1980 rec) 1956
A fallen old E-W fenceline is approx. 5 ft. south from BC mon.
1980 BT not found, falls in creek.
New - A 24" DBH D.Fir scribed "N¼ S5 CS" "BT" on a double blaze; bears N.71°E., 40.8 ft.
A 3" DBH W.Oak scribed "X" "CS BT" on a high low blaze (the lower blaze faces some what Estly of bearing to BC bears S.49½°E., 34.7 ft.
A 13" DBH I.Cedar scribed "N¼ S5 CS" "BT" on a double blaze; bears N.59°W., 23.0 ft.
Note - Monument is on moderate forested NE slope on West'ly side of draw of seasonal creek and approx. 150 N'thly from main BLM road.
Decl. 15¾°E