

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7216)

-----  
Set quarter sec. post, from which  
A Laurel 4" dia., bears S.30°E., 20 lks. dist.  
A Laurel 2" dia., bears N.35°W., 28 lks. dist.

Douglas Co. Surveyors Office - James Byron, Co. Surveyor - John M. Powell and crew - Jan. 7, 1971 - C.S. File 54/120

-----  
Set by survey by proportionate measurement.  
Set Brass cap at cor. mkd: County Surveyor's T30S R6W  
Office 1971  $\frac{1}{4}$   $\frac{S \ 16}{S \ 21}$   
New BTs -30" D.Fir N.59°E., 22.3 ft. mkd.  $\frac{1}{4}$  S16 CSBT.  
48" D.Fir S.45°E., 42.6 ft. mkd.  $\frac{1}{4}$  S21 CSBT.

Found OK Oct. 1998 by G. Nygren - M129-23

Ron Quimby - For: Guy Kennerly - 4/2008 - M146-73

-----  
Found - DCSO brass cap (per 1971 ren) bent, location was taken were pipe went into the ground.  
30" D.Fir snag, N.59°E., 22.3'  
48" D.Fir S.45°E., 42.6'  
New - 16" D.Fir N.50°W., 9.2'  
14" D.Fir N.90°W., 20.8'  
14" D.Fir S.28°W., 21.4'  
All new BTs scribed " $\frac{1}{4}$  S BT"