

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 4 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6459)

Set ¼ sec. post, at proper dist., from which
A R.Fir 10" dia., bears N.20°W., 6 lks. dist.
A R.Fir 8" dia., bears S.5°E., 20 lks. dist.

BLM resurvey by Thielsen and White, under Group #'s 348 and 350. Surveyed July 1958/Aug. 1959 (DCSO records, Vol. 30 Pages 12810-11)

Point for the ¼ sec. cor. of sec. 4, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd:

¼ S 4
T 30 S R 6 W
1958

from which

A Fir 8" dia., bears S.3°E., 70 lks. dist., mkd. ¼ S4 BT.
A Fir 8" dia., bears S.57°W., 55 lks. dist., mkd. ¼ S4 BT.

BLM resurvey by Jelley and Rogers, under Group #'s 1024 and 1039. Surveyed April/Oct. 1980 (DCSO records, Vol. 42 Pages 16561/62)

Point for the 1/4 sec. cor. of sec. 4 only, at proportionate distance; there is no remaining evidence of the original cor. From the point, the ¼ sec. cor. of sec. 4 only, erroneously reestablished by Thielsen and White, in 1958-59, bears S.4°50'E., 0.06 chs. dist., monumented with an I.P., set and marked and witnessed as described in the official record.

I remove the iron post, and at the corner point:
Reset the Iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

1/4 S 4
T 30 S R 6 W
1958
1980

from which the remains of BTs mkd. by Thielsen and White

A sawed Fir stump 14" dia., bears S.2½°E., 72 lks. dist., with healed blaze.
A Fir 16" dia., bears S.55½°W., 56½ lks. dist., with healed blaze.

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 4 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM rehabilitation of certain corners, Timothy J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying Tech., under Group #2000, Surveyed June 2002, - (DCSO records Vol. 54 Page(s) 21148-9)

The ¼ sec. cor. of sec. 4 only, on the N. bdy of the Tp., monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with brass cap mkd.

¼ S 4
T30S R6W
1958
80

from which the remains of a BT mkd. by Thielsen & White and reported by Jelley & Rogers

A fir snag, 18" dia., bears S.50°W., 38.6 ft., with a healed blaze. (Record S.55½°W., 37.3 ft.)

and a bearing tree not of record

A fir, 11" dia., bears S.34¾°E., 9.1 ft. with a healed blaze.

and a new bearing tree

A fir, 8" dia., bears S.66°W., 11.5 ft. mkd. ¼ S4 BT. Each new bearing tree has a 2½"x ¼" magnetic nail (Mag-Nail) driven at the base right side-center.

The geographic position (NAD 1983 (CORS)) of this cor. as determined by NAVSTAR Global Positioning System (GPS), utilizing dual frequency, carrier phase GPS receivers, (Trimble 5700), relative to the National Spatial Reference System, is as follows:

Latitude: 42°59'55.43"N., Longitude: 123°24'57.96"W.