

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

S.23°W., 108.2 ft. (Rec. S.25°W., 108.2 ft.)
Orig. BT.
14" now 18" dia. Ponderosa Pine with illegible
scribe marks visible on a partially healed double
blaze, bears S.22°E., 24.4 ft. (Rec. S20°E., 24.4
ft.)
15" pine now down and rotted with scribe marks
visible on open double blaze "¼ S10 CS BT" bears
N.31°W., 56.5 ft. to root hole. (Rec. N.26°W.,
56.5 ft.)
10" Ponderosa Pine with a single blaze, scribing
visible "¼ S10 BT" bears N.59°W., 30.4 ft.
(agrees well with record.)
Set - The "2" from the improper 1963 stamping "S12" is
stamped out and an "0" and "1989" are added to
brass cap.
New BT - 17" dia. Ponderosa Pine, fence corner, single blazed
and scribed 4½ ft. above ground "¼ S11 CS BT"
bears N.3½°E., 5.6 ft.
Corner lies on a NE-SW ridge that slopes southwest.

Cor. Fd. and Used in BLM Resurvey by Dale Bedell, under Group
#1551, Surveyed Aug. 1990/July 1991 (DCSO Records, Vol. 50
Page 19205)