

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 and 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page 7207)

-----  
Set quarter sec. post from which  
B.Oak 14" dia., bears S.10°W., 400 lks.  
B.Oak 14" dia., bears N.40°W., 380 lks.

F. Cain - For: J.D. Cornutt - Feb. 4, 1920 - Vol. 2 Pg. 273 and Field Book 107 Pg. 18

-----  
Renewed from which  
A W.Oak 30" bears S.41°05'W., 2.32 chs.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby; - Dec. 1963 - C.S. File 53/40-29

-----  
Found - 34" W.Oak S.41°W., 153.1 ft. Open & fd good scribing  
Set Brass cap at cor. mkd: County Surveyors  $\frac{1}{4}$  S11 T30S R6W  
Office 1963 S14  
Rescribe 34" W.Oak S.41°W., 154.1 ft. " $\frac{1}{4}$  S14 CS BT".  
No trees near North of section line. (See CS file for sketch of fence relationship)

Robert Mason - For: Robert Thompson - Feb. 14, 1981 - C.S. File 58/255(N) - M 87-10

-----  
Found - DCSO Brass cap on 1" I.P. (1963)  
36" W.O. S.41½°W., 155.0'.  
42" B.O. N.41½°W., 248.1' (OBT?)

Fd. & Used in BLM resurvey by Dale Bedell, under Group #1551, Surveyed Aug. 1990/July 1991 (DCSO rec. Vol. 50 Page 19203)

Bruce Shaner - For: Roseburg Resources Co. - June 2002 - M137-44 & C.S. File 65/44-6H

-----  
Found - 1" iron pipe with 2½" brass cap, properly mkd., from which a:  
42" W.Oak, face overgrown, bears S.41½°W., 155.0 ft.  
48" W.Oak, face overgrown, now blown down, bears N.41½°W., 248.1 ft. (This was an orig. BT)  
No BTs within reasonable dist. in Sec. 11  
Set - 6 ft. steel fence post bears North 1.0 ft.  
6 ft. steel fence post bears West 1.0 ft.  
Corner lies North 12 ft. & West 2 ft. from fence corner. Fence runs N & W from fence corner.

Fd. Ok by K. DeGroot, 12/2005, M146-32