

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7235-36)

Set ¼ sec. post, from which
A Fir 8" dia., bears N.60°E., 8 lks. dist.
A Fir 8" dia., bears S.82°W., 18 lks. dist.

Survey by Howard W. Johnstone - For: Roseburg Lumber Co. - May 28, 1962 - C.S. File 51/163-2

Found - 8" Fir N.60°E., 8 lks., badly burned.
8" Fir S.82°W., 18 lks., good condition.
Set 1¼" x 24" iron pipe, from which scribed
10" D.Fir S.44½°E., 21.6 ft.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2191, Surveyed April/May 2008 - (DCSO records Vol. 56 Page(s) 22135-6)

The ¼ sec. cor. of secs. 13 and 14, perpetuated by Johnstone, in 1962, monumented with an iron pipe, 24" long, 1¼" dia., firmly set, projecting 11" above ground, from which the remains of the original bearing trees

A decayed fir stump, 20" dia., bears N.60°E., 5.3 ft. with no marks visible.

A burnt, decayed fir stump, size indeterminate, bears S.82°W., 11.9 ft., downhill of which is a down fir snag, 12" dia., with no marks visible on an open blaze. and the remains of bearing trees mkd. by Johnstone

A roothole, bears S.44½°E., 20.1 ft., alongside of which is a down fir snag, 12" dia., with fragmentary scribe marks visible on a burnt, partially healed blaze.

At the cor. point

Set a stainless steel post, 28" long, 2½" dia., 26" in the ground, with brass cap mkd.

T30S R7W

¼

S 14 | S 13

2008

from which new bearing trees

A pine, 9" dia., bears N.1¼°E., 23.7 ft., mkd. ¼ S13 BT.

A fir, 13" dia., bears S.85½°W., 32.7 ft., mkd. ¼ S14 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Place the iron pipe inside the stainless steel post and deposit a magnet in a white plastic case at the base of the stainless steel post.