

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and new bearing trees
A fir, 5" dia., bears N.47¼°E., 12.9 ft., mkd.¼ S27 BT.
A fir, 5" dia., bears S.7°E., 4.5 ft., mkd.¼ S34 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail)
driven at the base right side-center.

Tony Hostetter - For: Weyerhaeuser Co - Nov. 2008 - M158-40

Found - 1965 DCS0 brass by Tracy.
4" Fir, scribing visible, 2007 BLM BT, bears
N.47½°W., 12.9 ft to mag nail, right side
center.
20" Fir, face evident, BLM tag, bears S.63°E. 15.0
ft
6" Fir, scribing visible, BLM 2006, bears S.7°E.,
4.5 ft. to mag nail, right side center.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral
Surveyor, under Group No. 2972, surveyed May 2020/Feb2021 -
(DCS0 records Vol. 59 Page(s) 23950-1)

The ¼ sec. cor. of secs. 27 and 34, reported by Saveland in
June through July of 2008, monumented with an iron post, 1¼"
dia., firmly set, projecting 7" above ground, with a brass
cap (properly) mkd.
from which the remains of an original bearing tree
A roothole bears N.24°W., 17.2 ft., downhill of which is
a down fir, 23" dia., with a healed blaze.
and the remains of the bearing trees reported by Saveland
A fir, 7" dia., bears N.47¼°E., 12.9 ft., with a healed
blaze.
A roothole bears N.48½°E., 37.1 ft., alongside of which is
a down fir, 19" dia., with a healed blaze.
A decayed pine snag, 15" dia., bears S.57½°E., 10.7 ft.,
with a healed blaze.
A fir, 7" dia., bears S.7°E., 4.5 ft., with a healed
blaze.
A roothole bears S.25°W., 16.5 ft., downhill of which is
a down cedar, size indeterminate, with scribe marks BT
visible on open blaze. (Original)