

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7317)

Set a fir post, 4 ft. long, 3" sq., 20" in the ground, for ¼ sec. cor., marked ¼ S on the N side and from which
A fir, 12" dia., bears S.80°E., 17 lks., mkd: ¼ S BT.
A fir, 10" dia., bears N.9°W., 36 lks., mkd: ¼ S BT.

Howard W. Johnstone - For: Roseburg Lumber Co. - May 28, 1962 - C.S. File 51/163-3

Found - 12" Fir S.80°E. 17 lks. (good)
 10" Fir N.9°W. 36 lks. (down)
Set - 1" by 24" Iron Pipe
Scribed- 16" W.Fir S.62°E. 27.0 ft.
 22" D.Fir N.62½°W. 56.3 ft.

BLM dependent resurvey by Wayne L. Rogers, Lance J. Bishop, and James L. White, Cadastral Surveyors under Group No. 1240 surveyed Feb/July 1985 - (DCSO records Vol. 47 Page(s) 18109-10)

The ¼ sec. cor. of secs. 24 and 25, perpetuated and recorded by Johnstone, in 1962, monumented with an iron pipe, 1" dia., firmly set, projecting 12", above ground, from which the remains of an original bearing tree:
A sawed fir stump, 30" dia., bears S.80°E., 17 lks., no marks visible.
and the remains of bearing trees mkd. by Johnstone
A sawed fir stump, 16" dia., bears S.62°E., 40 lks., with scribe marks ¼ S visible on a partially healed blaze (alongside of which is a down fir, 16" dia., with scribe marks BT visible on a partially healed blaze.)
A sawed fir stump, 27" dia., bears N.62½°W., 85 lks., with scribe marks BT visible on partially healed blaze.
At the corner point
Set an iron post, 30" long, 2½" dia., with magnetic, plastic breakaway base, 26" in the ground, with brass cap mkd.
 T30S R8W
 ¼ $\frac{S\ 24}{S\ 25}$
 1985
and new bearing trees
A fir, 16" dia., bears N.74¼°E., 21 lks., mkd. ¼ S24 BT.
A G.Fir, 9" dia., bears S.40½°W., 130 lks., mkd. ¼ S24 BT.
Deposit the iron pipe alongside the iron post.

continued next page

1

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Greg Lang - 5/3/2004 - C.S. File 65/49-32

Found - 2½" brass cap set by BLM
 20" D.Fir bears N.74½°E. 13.86' healed. BLM 1985
 13" W.Fir bears S.40½°W. 85.8' healed. BLM 1985
New - 8½" D.Fir bears S.57°E. 29.5' scribed "¼ S25 BT"
 10" D.Fir bears N.43¾°W. 45.5' scribed "¼ S24 BT"
Note - Corner lies on Northerly slope on the Westerly
 side of a drainage & South of old skid rd.

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 4/2014 - C.S.
File 65/82-34

Found - BLM brass cap
 24" Fir N.74°E. 13.9 ft. good scar.
 12" Fir S.59°E., 29.5 ft. good scar.
 18" Fir S.41°W., 85.8 ft. good scar.
 12" 7' tall fir stump N.44°W., 45.5 ft. vis. scribes
 ¼ S24 BT.
No trees available to NW
Note - Corner is in the SE cor. of newly logged unit.
 Compass decl. 15½°E.