

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias	Description

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7445)

A Fir, 6" dia., which I mark ¼ S on N side, for ¼ sec. cor., from which
 A laurel, 12" dia., bears S.17¾°W., 6¼ lks., mkd: ¼ S BT.
 A W.Fir, 6" dia., bears N.58°E., 13 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - Oct. 1964 - C.S. File 53/53-48

Found - 6" now 20" fir for corner tree, shows faint scar on N side.
 Orig. 6" now 20" W.Fir N.58°E., 8.6 ft. open & shows "4" scribe.
Set - 1" IP & brass cap on N side at base of corner tree mkd: COUNTY SURVEYORS OFFICE 1964 T30S R9W ¼ S17/S20
New BTS- 20" W.Fir N.58°E., 8.6 ft. (Orig.) mkd: ¼ S17 CS BT.
 18" D.Fir S.46°W., 31.8 ft. mkd: ¼ S20 CS BT.

Forest LaFlamme - Aug. 16, 1971 - C.S. File 55/209

I scribe a D. Fir 11" S.24°W., 49.6 ft. "¼ S 20 BT"

Gary Smither - For: Moore Mill Co. - Jan. 2001 - M136-54

Found - 1964 County brass cap/iron pipe firmly set in mound of stone per 1964 ren.
 16" Fir snag cor. tree has been pushed out w/cat bears S.80°W., 4.0 ft. & is falling over.
 31" W.Fir N.58°E., 8.6 ft.
 18" D.Fir S.46°W., 31.8 ft. is gone.
 11" D.Fir S.24°W., 49.6 ft. is a rotted stump.
New BTs- 8" D.Fir S.11°E. 40.5 ft to spike side center scribe "X" at breast height & "BT" at base with alum tag
 22" W.Fir N.17°W., 31.7 ft. to spike side center scribe T30 R9 ¼ S17 BT w/alum. tag
 15" D.Fir N.86°W., 32.0 ft. to spike side center scribe T30 R9 ¼ S17 BT w/alum. tag

BLM dependent resurvey by Herman A. Pieske, Registered Land Surveyor #1651, No. YA-553-CT2-67, under group #1107, surveyed July 1982/Feb 1983 - (DCSO rec. Vol. 48 pg 18300-1)

The Cor. of secs. 17 & 20 perpetuated & recorded by Tracy in 1964, monumented with an iron post, 1" dia., firmly set projecting 10" above ground, with brass cap (properly) mkd
 continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which the remaining orig. BT
A W.Fir, 25" dia., bears N.58°E., 13 lks., with healed blaze.
and a BT mkd. by Tracy
A fir stump, 11" dia., bears S.24°W., 75 lks., with scribe marks ¼ S20 BT visible on open blaze.
and a new BT
A cedar, 17" dia., bears S.44°E., 90 lks., mkd: ¼ S20 BT.

BLM dependent resurvey by Randolph E. Younis, Cadastral Surveyor, under Group No. 2849 - surveyed Sept. 2016/March 2017 - (DCSO Records Vol. 59 Page(s) 23621-2)

The ¼ sec. cor. of secs. 17 and 20, perpetuated by LaFlamme, in 1971; further perpetuated by Smither, in January 2001; monumented with an iron post, 1½" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd. from which an original bearing tree
A fir, 34" dia., bears N.58°E., 8.6 ft., with a healed blaze.
and the remains of a bearing tree mkd. by LaFlamme
A badly decayed fir stump, 8" dia., bears S.23¾°W., 49.9 ft., no marks visible.
and the remains of the bearing trees mkd. by Smither
A fir, 10" dia., bears S.13°E., 40.0 ft. to spike found in left side center, with a hacked X at breast height and healed blaze at base.
A fir high stump, 18" dia., bears N.88¼°W., 32.2 ft., with a healed blaze.
A fir, 24" dia., bears N.19¾°W., 31.9 ft. to spike found in left side center, with a healed blaze.
and a new reference monument
An iron rod, 30" long, 5/8" dia., set 28" in the ground for a reference monument, bears N.71°00'08"W, 31.16 ft., with aluminum cap mkd. RM T30S R9W ¼ S17 31.2 FT TO COR 2016 and an arrow pointing to the cor.