

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. cor)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7459)

-----  
Set post, cor. tps. 31 and 32 S., Rs. 1 and 2 W., from which  
A Fir 18" dia., bears S.80°E., 14 lks. dist.  
A Fir 10" dia., bears S.67°W., 24 lks. dist.  
A Fir 10" dia., bears N.74°W., 22 lks. dist.  
A Laurel 10" dia., bears N.50°E., 11 lks. dist.

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747,, dated May 5, 1902 - (DCSO records Vol. 18 Page(s) 7608-09)

-----  
The SW Cor. of T31S R1W, which is a post badly decayed, marked and witnessed as described by the surveyor general with the exception of the NE tree which has been destroyed. I reestablish this cor. at the same point as follows:  
Set a new Fir post 8" sq. 3 ft. long, 24" in the ground for cor. of township 31 S., R1W and 2 West, marked T31S R1W S31 on NE., T31S R2W S36 on NW. faces, with 6 notches on N, E, and W. edges, from which  
A Fir 30" dia., bears N.30°E., 58 lks. dist. mkd. T31S R1W S31 BT.  
A Fir 12" dia., bears N.75°W., 24 lks. dist. mkd. T31S R2W S36 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 (DCSO records Vol. 18 Page(s) 7582)

-----  
The Cor. of Tps. 31S., Rs. 1 and 2 W., which is a Cedar post, 4" sq., firmly set, extending 12" above the ground, marked T31S R1W S31 on NE. and T31S R2W S36 on NW. face, with 6 notches on N., E., and W. edges, from which  
A Fir 30" dia., bears N.30°E., 58 lks. dist., mkd. T31S R1W S31 BT. (Old BT)  
The old bearing tree in sec. 36 is dead and fallen.  
A Fir 14" dia., bears N.33°W., 29 lks. dist., mkd. T31S R2W S36 BT. (New BT)

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Terry Connell, crew - July 1966 - C.S. File 54/28-46

-----  
Found - Orig. 30" Fir N.30°E., 38.3 ft., shows good scar.  
Orig. 14" Fir, now down, N.33°W., 19.1 ft. scribe visible, "R2W BT".  
(Cont. Next Page)

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. Cor.)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set Brass cap at cor. mkd: County Surveyors Office  
R T 31 S R  
2 S 36 | S 31 1  
W S 1 W  
1966  
New BT - 24" D.Fir N.19°W., 34.6 ft. mkd. T31S R2W S36 CS BT

Fd. OK, July 1978 by G. Baughman - C.S. File 58/173