

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7474

Set ¼ sec. post, from which
An Oak, 18" dia., bears S.28°W., 18 lks.
A pine, 40" dia., bears N.47°E., 40 lks.

Robert M. Thompson - July 29, 1956 - C.S. File 42/252

I find the 2 orig. BTs as described in orig. GLO field notes, but both dead.
I renew by scribing new BTs:
16" D.Fir N.19°40'W., 17.3 ft.
16" D.Fir S.48°10'E., 14.9 ft.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Sept. 1968 - C.S. File 54/71-64

Found - Two orig. BT as described by GLO BT as described by GLO field notes. Plus the renewed BTs by Robert Thompson in 1956.
Orig. 40" S.Pine, now 44" Windfall, N.47°E., 26.4 ft., shows scribing.
Orig. 18" Oak, now 26" snag, S.28°W., 11.9 ft., shows poor face.
16", now 18" D.Fir N.19°40'W., 17.3 ft., shows good scribing of (¼ S19 & Part of BT)
16" now 18" (rec. D.Fir) S.48°10'E. 14.9 ft., N, BT, shows good scribing of (¼ S20 & Part of BT)
Set brass cap at cor. mkd: COUNTY SURVEYORS T31S R1W
OFFICE 1968 ¼ S 19|S 20
Note - This ¼ corner lies on general east slope.