

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 18

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7475  
-----

Set 1/4 sec. post, from which  
An Oak, 12" dia., bears N.45°W., 51 lks.  
An Oak, 10" dia., bears N.40°E., 41 lks.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1968 - C.S. File 54/71-89  
-----

Found - 12" Oak, now rotten stump, N.45°W. 33.7 ft., opened stump for scribe "BT".  
10" Oak, now stump hole, N.40°E., 27.1 ft.  
Set - Brass Cap at Cor. mkd: County Surveyors T31S R1W Office, 1968 ¼ S 18|S 17  
New BTs- 10" Cedar N.40°W. 22.0 ft. scribed ¼ S18 CS BT.  
16" D.Fir N.67°E. 28.3 ft. scribed ¼ S17 CS BT.  
This corner lies west of draw about 80 ft.

Jonathan B. Drew, II, USFS - Assisted by: Lance Goucher - 4/20/2015 - C.S. File 65/90-15  
-----

Found - A 2½" DCSO brass cap on 1¼" galvanized iron pipe, projecting 7" above a small mound of stones. Leans slightly south. Note: "¼" and section number markings oriented north, all others are not.  
A 14" cedar with a healed double blaze. Rec. (N.40°W., 22.0 ft)1968  
A 22" fir with a healed double blaze. Rec. (N.67°E., 28.3 ft)1968  
No new accessories needed.  
Corner maintenance/other info - Clear brush from around monument and to BTs. Tie flagging to monument and guard posts, paint BT faces & a 6" band at head height, add new nails to existing BT tags & add new tags where needed.  
Geodetic coordinates -  
Lat: N. 42°52'48.377" Long: W. 122°51'48.653"  
Datum - WGS 84  
Source - USGS QUAD map, for navigation to corner.