

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7466-7

Set ¼ sec. post, from which
An Oak, 10" dia., bears S.88°W., 31 lks.
A pine, 30" dia., bears N.24°W., 56 lks.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1968 - C.S. File 54/71-91

Found - 10" B.Oak, now cut stump, S.88°W., 20.5 ft., opened stump for scribe.
30" Pine, now down, N.24°W. 37.0 ft.
Set - Brass Cap at Cor. Mkd: County Surveyors T31S R1W
Office 1968 ¼ S 21
S 28
New BTs- 8" Fir West 11.3 ft. Mkd: ¼ S28 CS BT.
10" Fir N.20°W. 9.0 ft. mkd: ¼ S21 CS BT.
Note - This corner lies west of old picket fence about 20', fence runs N-S.

John Ransom, USFS - Jonathan Drew - 11/2013 - C.S. 65/85-16

Condition report
Found - 2½" DCSO brass cap (properly mkd) on 1¼" iron pipe, projecting 18" above a mound of stone.
13" Fir (West) (11.3 ft) healed double blaze
14" Fir (N.20°W.) (9.0 ft) healed double blaze
() = Record per 1985 corner card by: L. Moffit
No new accessories added
New nails in BT tags and painted faces & 6" band at head height
Note - Corner falls on level ground about 150 feet north of a creek. To access corner follow 1610-370 road to line crossing in center of section 28, follow posted/blazed line north 2000 feet ± to corner. Brush cleared around monument and to BTs
"LAND LINE" Flagging tied on monument and guard posts
Property line maintained south .5 miles and north .5 miles.