

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 21 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7467

Set ¼ sec. post, from which
 A fir, 18" dia., bears S.10°E., 24 lks.
 A fir, 18" dia., bears N.50°W., 59 lks.

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7540-1)

The ¼ sec. cor., located by record measurement from the orig. BTs. From cor. point
 A fir, 34" dia. bears S.10°E. 24 lks. mkd: ¼ S BT (Old BT)
 A fir, 34" dia. bears N.54°W. 59 lks. mkd: ¼ S BT (Old BT)
I now change this cor. to refer to sec. 21 only, and obliterate the marks on the BT referring to sec. 22.
At exact cor. point
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 21 only, with brass cap marked
 ¼ S21 |
 1923 |
from which
 A fir, 18" dia., bears S.50°W., 30 lks., mkd: ¼ S21 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Oct. 1968 - C.S. File 54/71-68

Found - GLO Brass Cap & 3 BTs.
 Orig. 34", now 44" D.Fir, S.10°E., 15.8 ft., shows good face. (This BT is reference as BT to ¼ Cor. Sec. 22 only by GLO Field Notes.)
 Orig. 34", now 39" D.Fir, N.54°W., 38.9 ft., shows good face.
 20", now 26" D.Fir, S.68°W., 23.5 ft., opened & fd. scribing. (This BT is same age as others, but is not recorded in field notes.)
Note - We found the brass cap for ¼ of S22 only in place of the ¼ of 21 only. We switch the brass caps around so they are in the right places, now reads as follows: Reset GLO brass cap at the ¼ cor S21 only (properly) mkd
Rescribed BT - 26" D.Fir S.68°W., 23.5 ft. mkd: ¼ S21 CS BT.
Note - This ¼ corner of Sec. 21 only lies 7.9 ft. N. of ¼ Cor. Sec 22 only.
These caps were orig. placed in the wrong location & facing south. We dig them up and replace them in the right places facing north. The caps now refer to the right sections.

