

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7566-7)

-----  
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked

1/4  
S 22|S 23  
1923

from which

- A fir, 10" dia., bears S.86°E., 21 lks., mkd: 1/4 S23 BT.
- A fir, 16" dia., bears S.83°W., 63 lks., mkd: 1/4 S22 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug./Sept. 1968 - C.S. File 54/71-132

-----  
Found - No trace of 1923 GLO Brass Cap, after diligent search with a metal finder.

10", now 15" R.Fir, S.86°E., 13.9 ft., scribe visible.

16", now 20" R.Fir, S.83°W. 41.6 ft. shows good scar

Set - Brass Cap at Cor. Mkd: County Surveyors T31S R1W  
Office, 1968 1/4 S 22|S 23

All Bearing Trees OK and Tagged.