

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7570)

-----  
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 10, 11, 14, & 15, with brass cap mkd

T31S R1W  
S 10|S 11  
S 15|S 14  
1923

from which

- A hemlock, 18" dia., bears N.65°E., 29 lks., mkd: T31S R1W S11 BT.
- A hemlock, 8" dia., bears S.41°E., 52 lks., mkd: T31S R1W S14 BT.
- A fir, 28" dia., bears S.22°W., 20 lks., mkd: T31S R1W S15 BT.
- A hemlock, 8" dia., bears N.22°W., 29 lks., mkd: T31S R1W S10 BT.

Douglas Co. Surveyors Office - John M. Powell & Vernon "Ray" Tracy - Aug. 1968 - C.S. File 54/71-96

-----  
Found - 1923 GLO Brass Cap, out of ground. Replaced Brass Cap at Sec. Cor.  
18" Hemlock, now stump, N.65°E., 19.1 ft., opened for scribed.  
8", now 10" Hemlock, S.41°E. 34.3 ft., shows good scar.  
28" D.Fir, now stump, out of place.  
No trace of NW BT.

New BTs- 48" D.Fir S.15°W., 64.4 ft. scribed T31S R1W S15 CS BT.  
38" D.Fir N.16°E., 41.0 ft. scribed T31S R1W S11 CS BT.  
12" R.Fir N.7°W., 50.4. ft. scribed T31S R1W S10 CS BT.