

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; S. 24, T31-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7794)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. mkd. ¼ S on W. face; from which
A Fir 10" dia., bears N.50°W., 17 ¾ lks. dist. mkd. ¼ S BT.
A Fir 10" dia., bears N.12¼°E., 11 lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - Wit: R.G. Boyd - For: Stomar Lumber Co. - April 28, 1959 - C.S. File 42/391-21

At midpoint, SET 5/8" x 30" Iron rod, from which
7" Laurel bears S.45°E., 18.5 ft. mkd. ¼ S19 T31S R3W BT.
10" Fir bears S.75°E., 9.3 ft. mkd. ¼ S19 X BT.
5" Fir bears N.58°W., 12.5 ft. mkd. ¼ S24 BT.
5" Laurel bears West 20.3 ft. mkd. ¼ S24 T31S BT.
Road bears North 340.0 ft.

David Edwards - For: Roseburg Resources Co. - Feb. 2011 - M162-12

Set - 5/8"x30" steel rebar with 2½" dia., alum cap mkd. as per BLM manual and marked "ROSEBURG RESOURCES CO" "LS 2339" "2011"
An 8" dia. Cedar bears S.34°E., 17.6 ft.
An 8" dia. Madrone bears N.7°1W., 14.1 ft.
A 6 ft steel post is set 2' west.
The 5/8" dia. IR per C.S. 42/391 bears S.17°52'32"E., 52.28'.
Note- (Set E¼ Corner by proportionate measure) Monuments set by Markham in 1958 (see field notes in C.S. file 42/391), are significantly out of position and are therefore disregarded.