

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 5 of T32-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7687)

Set ¼ sec. post, from which
A Laurel 5" dia., bears N.50°W., 50 lks. dist.
A Fir 40" dia., bears S.85°E., 15 lks. dist.

George Wenderoth - Aug. 1942 - C.S. File 46/133

No BT found so run line between SW. and SE. corner and set ¼ corner equal distance from each.
Set 1" iron pipe 30" long, from which 2 new BTs:
A 7" Chinquapin S.47°24'E., 9.2 ft.
A 10" Fir N.47°40'W., 33.9 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan. 1966 - C.S. File 52/63-55

Found - Iron pipe at 1/4 corner.
7" Chinquapin now 10", S.47°E., 9.2 ft., opened for scribed "BT".
10" Fir now 14" N.47½°W., 33.9 ft, shows good scars.
Dist. should be 34.9 ft.
Set brass cap alongside I.P. & mkd: County Surveyors Office
T 31 S
¼ $\frac{S\ 32}{S\ 5}$ R3W
T 32 S
1966
New BT - 8" D.Fir S.60°W., 33.0 ft. scribed ¼ S5 CS BT.

Fd. B.C. & BTs, Aug. 1991 by G. Nygren - M 114-7

Fd. Ok by M. Heimbürger - 7/2001 - M138-35