

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7739)

A Fir 15" dia., which I mark $\frac{1}{4}$ S on W. face for $\frac{1}{4}$ sec. cor., from which

A Fir 15" dia., bears East, 25 lks. dist. mkd. $\frac{1}{4}$ S BT.

A Fir 15" dia., bears S.45 $\frac{1}{2}$ °W., 21 $\frac{1}{2}$ lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb. 1966 - C.S. File 52/63-85

Found - 15" Fir, " $\frac{1}{4}$ S" on W. face, Corner tree, opened for scribe "S".

Orig. D.Fir, blown down and out, East 16.5 ft.

Orig. 15" now 30" D.Fir, S.45 $\frac{1}{2}$ °W., 14.0 ft., shows scar low on tree.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 3 W

$\frac{1}{4}$ S21 | S22

1966

New BT - 12" D.Fir N.55°E., 33.0 ft. scribed $\frac{1}{4}$ S22 CS BT.

Gregg Neitsch - For: Carbon River Holdings LLC - 6/2022 - M181-10

Found - 1" I.D galvanized iron pipe set in rotted fir stump with a 2 $\frac{1}{2}$ " BC (properly mkd), 16" above ground, from which bears:

42" DF with logging scars S.45 $\frac{1}{2}$ °W., 14.0'

(New?) - 6" DF with alum. tag stamped "PLS 7662" nailed inlow blaze N.59 $\frac{1}{4}$ °E., 12.5'