

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7850)

-----  
Set a stone 20x10x9 ins., 15" in the ground, for cor. to secs. 29, 30, 31 and 32, marked with 5 notches on E. and 1 notch on S. edges; from which

A Laurel 12" dia., bears N.69¼°E., 26½ lks. dist. mkd. T31S R4W S29 BT.

A Fir 10" dia., bears S.16½°E., 19 lks. dist. mkd. T31S R4W S32 BT.

A Fir 15" dia., bears S.12 3/4°W., 14 lks. dist. mkd. T31S R4W S31 BT.

A Fir 15" dia., bears N.74°W., 26½ lks. dist. mkd. T31S R4W S30 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - March 1966 - C.S. File 54/20-22

-----  
Found - No sign of stone, but found iron pipe, unrecorded.  
Orig. 12" Laurel, now rotten stump, N.69°E., 17.5 ft  
Orig. 10" Fir, now rotten stump S.16½°E., 12.5 ft.  
Orig. 15" Fir now 27" S.12 3/4°W., 9.2 ft. shows good scar.

Orig. 15" Fir now 31" N.74°W., 17.5 ft. shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

S 30 | S 29

S 31 | S 32

1966

New BTs- 37" D.Fir N.86°E., 6.0 ft. scribed T31S R4W S29 CS BT.

38" D.Fir S.48°E., 27.2 ft. scribed T31S R4W S32 CS BT.

Fd. and used in BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under Group #1217, surveyed Sept. 1984/April 1986 - (DCSO records Vol. 47 Page(s) 18153)