

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 209700

PRIMARY CORNER DESCRIPTION Angle point on So. bdy. Sec. 32, T30-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6985)

-----  
Set a post at proper distance for cor. to secs. 5, 6, 31 and 32, from which

- A Red Fir 7" dia., bears S.20°E., 12 lks. dist.
- A Red Fir 10" dia., bears S.5°W., 18 lks. dist.
- A Red Fir 12" dia., bears N.35°W., 14 lks. dist.
- A Red Fir 18" dia., bears N.40°E., 22 lks. dist.

(Note: As noted by Thiel in 1889, the above corner by Ford must have been in doubt as Thiel states in Vol. 17 Pg. 7024 "In order to be sure that Deputy Ford did not run the South bdy. of this Tp. and set any Cors., I went to the cor. of Tps. 30 and 31 S., R.5 W. on the offset Meridian line - - - - -") V. Laugen, March 1996

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7022)

-----  
Set a Fir post 4½ ft. long, 4" sq., 24" in the ground, for cor. to secs. 32, 31, 5 and 6, marked T30S S32 on NE.; R4W S5 on SE.; T31S S6 on SW.; S31 on NW. faces with 5 notches on E. and 1 notch on W. edges, from which

- A Fir 27" dia., bears N.31°E., 9 lks. dist. mkd. T30S R4W S32 BT.
- A Fir 10" dia., bears S.13°E., 41 lks. dist. mkd. T31S R4W S5 BT.
- A Fir 24" dia., bears S.63½°W., 22 lks. dist. mkd. T31S R4W S6 BT.
- A Fir 42" dia., bears N.35°W., 62 lks. dist. mkd. T30S R4W S31 BT.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 17 Page(s) 7124-25) and Vol. 19 Pg. 7875)

-----  
(Page 7124) (Tied to and described Thiel's corner)  
"As this closing is not within the prescribed limits I go to the cor. established for secs. 4, 5, 32 and 33."  
(Page 7125) and (Vol. 19 Pg. 7875)  
The cor. to secs. 5, 6, 31 and 32.  
As this is not a corner to secs. 31 and 32, I destroy the mark on the NE. and NW. faces of this cor. and the marks on the witness trees North of this line in T30S R4W.

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 209700

PRIMARY CORNER DESCRIPTION Angle point on So. bdy. Sec. 32, T30-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under group #1217, surveyed Sept. 1984/April 1986 - (DCS0 records Vol. 47 Pages 18133-34)

-----  
The cor. of secs. 5, 6, 31 and 32, determined from the remains of the original bearing trees:

A sawed Fir stump 30" dia., bears N.45°E., 9 lks. dist., with scribe marks BT visible on opened blaze. (Rec. N.31°E.)

A sawed, decayed Fir stump, size indeterminate, bears S.63½°W., 22 lks. dist., no marks remain.

A sawed Fir stump 50" dia., bears N.35°W., 56 lks. dist., with scribe marks T30S R4W BT visible. (Rec. 62 lks.)

This point now becomes an angle point.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

AP  
T 30 S R 4 W  
S 32  
S 5  
T 31 S  
1985

from which a new bearing tree

A Fir 14" dia., bears N.77 3/4°E., 74 lks. dist., mkd. AP S32 BT.

No suitable trees available in sec. 5.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Fd. OK, April 1996 by Ken Hoffine - M 123-69

Ken Hoffine - For: Lone Rock Timber Co. - Nov. 2013 - M 166-6 & C.S. File 65/81-1

-----  
Found - 1985 BLM cap 0.2 feet above ground  
30" fir stump bears N.42°E., 5.75 ft as per record chopped out face and tag.  
Rotten remains bears S.62½°W., 15.4 ft as per record  
22" D.Fir bears N.76°E., 48.5 ft (record N.77¾°E., 48.8 ft) healed face  
14" D.Fir bears S.43°W., 21.05 ft we scribe AP S5 BT and tag tree.

Corner lies on steep SE slope approx. 115 feet East of 31-4-4.2 RD.

continued next page

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 209700

PRIMARY CORNER DESCRIPTION Angle point on So. bdy. Sec. 32, T30-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2872, surveyed April 2017/Oct. 2019- (DCSO records Vol. 59 Page 23835-6)

-----

An angle point bet. secs 5 & 32; formerly the cor. of secs. 5, 6, 31, and 32, perpetuated by Hoffine, in 2013, monumented with an iron post, 2½" dia., firmly set, with a brass cap (properly) mkd.

from which the remains of the original BTs, reported by Rogers, McMullen and Bishop in 1984-86

A decayed fir stump, 30" dia., bears N.45°E., 5.9 ft., with axe marks visible on bark.

A decayed fir stump, size indeterminate, bears S.63½° W., 14.5 ft., no marks visible.

A fir stump, 50" dia., bears N.35°W., 37.0 ft., with scribe marks 4W visible on bark.

and a BT mkd. by Rogers, McMullen, and Bishop in 1984-1986

A fir, 25" dia., bears N.77¾°E., 48.8 ft., with a healed blaze.

and a BT mkd. by Hoffine

A fir, 16" dia., bears S.43¾°W., 21.1 ft., with illegible scribe marks visible on partially healed blaze.