



TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 32; and S.5 of T32-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note: A search of DCSO records resulted in no record source being found for the "Fd. 1" I.P" mentioned in above corner visits. V.L. 12/13/94

Bruce Shaner - For: Seneca Jones Timber Co. - 12/96 - C.S.  
File 65/13-1 C - R.M. 4-3

-----  
Found - 2½" Brass Cap on a 1" iron pipe, from which a:  
5" Oak BT (now 12", dead & down), bears S.53°E. 7.9'  
All 3 other BT's now gone due to road construction.  
New BTs- 12" D.Fir, scribed "¼ S5 BT" bears S.17°E., 19.2'.  
10" Madrone, scribed "¼ S32 BT" bears N.59°W., 10.5'  
6 foot steel fence post, North 1.0 feet.  
Note - Corner is 25 feet East from USBLM rock. Road.

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor,  
under Group No. 2627; Surveyed April/May 2013 - (DCSO records  
Vol. 58 Page(s) 23065-6)

-----  
The ¼ sec. cor. of secs. 5 and 32, on the N. bdy. of the Tp.,  
perpetuated by Douglas County Surveyor's Office in 1966, from  
original evidence no longer in existence, and further  
perpetuated by Shaner, in 1996; monumented with an iron post,  
1" dia., firmly set, projecting 10" above the ground, with  
brass cap (properly) mkd.  
from which a bearing tree mkd. by persons unknown  
A ponderosa pine, 31" dia., bears N.64°E., 32.2 ft., with  
a healed blaze.  
and bearing trees mkd. by Shaner  
A fir, 16" dia., bears S.17¼°E., 18.8 ft., with a healed  
blaze.  
A madrone, 10" dia., bears N.55°W., 10.3 ft., with scribe  
marks ¼ S32 BT visible on bark.