

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7857)

Set a stone 16x11x4 ins., 12" in the ground for ¼ sec. cor. marked ¼ on N. face; from which

A Hemlock 7" dia., bears N.14°W., 24 lks. dist. mkd. ¼ S BT.

A Hemlock 6" dia., bears S.20½°E., 21 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - James W. Byron, Surveyor John Powell, and crew - C.S. file 54/20-37A & C.S. File 54/20-6A? - Feb 1966 & April 1966

Corner searched for, not found.

Tony Hostetter - For: Seneca Jones Tbr Co - 11/2007 - M154-51

Found - No evidence of corner or accessories.

Set - 5/8"x36" rebar w/alum. cap mkd: T31S R4W ¼ S20|S29 LS1975 2007, from which

12" Fir, scribed "S20 ¼ BT" bears N.48°26'E., 25.5 ft. to spike.

12" Yew scribed "S20 ¼ BT" bears N.54°56'E., 15.5 ft. to spike.

15" hemlock, scribed "S29 ¼ BT" bears S.57°34'E., 33.8 ft. to spike.

22" hemlock, scribed "S29 ¼ BT" bears S.44°17'E., 17.5 ft. to spike.