

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7789)

-----  
Set post, cor. to secs. 28, 29, 32 and 33, from which  
A Fir 14" dia., bears N.15°E., 34 lks. dist.  
A Fir 20" dia., bears S.50°E., 34 lks. dist.  
A Fir 16" dia., bears S.50°W., 21 lks. dist.  
A Fir 16" dia., bears N.42°W., 8 lks. dist.

Fd. and Used in GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7845)

Frank Cain - Sept. 20, 1909 - Field Book 10 Page 51½

-----  
Put in NW. cor. 33, old BTs badly decayed.  
Marked "CS" a Fir 12", S.76 3/4°E., 31 lks.  
Marked "CS" a Fir 12", S.32½°W., 59 lks.

Douglas Co. Surveyors Office - G.J. Wenderoth, Deputy - Wit:  
F. Loso - March 1949 - C.S. File 40/245

-----  
Found - Orig. 16" Fir, N.15°E., 22.4 ft.  
Orig. 18" Fir N.42°W., 5.8 ft.  
Orig. 18" Fir S.50°W., 13.8 ft.  
(Could not find trees set by Cain in 1909)  
Drive 1¼" Iron pipe.  
Marked - 40" Fir, S.13°15'E., 32.5 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan/Feb. 1966 - C.S. File 54/20-15

-----  
Found - Iron pipe at sec. cor.  
16" Fir N.15°E., 22.4 ft., shows good scar.  
18" Fir N.42°W., 5.8 ft., scribe visible "T31S R4W"  
18" Fir, now stump, S.50°W., 13.8 ft.  
40" Fir S.13°E., 32.5 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 4 W  
S 29 | S 28  
S 32 | S 33  
1966

New BT - 13" D.Fir S.66°W., 10.3 ft., scribed T31S R4W S32  
CS BT.

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and Used in BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15483)

FD. Ok by B. Shaner, 12/96 - C.S. File 65/13-1 N, & R..M. 4-3

Found OK by R. Rice, Feb. 2004 - M144-9