

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 33; and S.4, T32-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 18 Page(s) 7783)

Set ¼ sec. post, from which
A Fir 14" dia., bears N.10°W., 29 lks. dist.
A Fir 40" dia., bears S.80°W., 23 lks. dist.

Frank Cain - Sept. 1909 - Field Book 10 Page 51½

Set ¼ sec. post on South boundary of sec. 33 at 40.66 East of SW cor., from which
A Fir 12" bears S.77 ¾°W., 1.25
A Fir 36" bears N.38 ¾°W., 1.20½.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12788-89)

The ¼ sec. cor., determined at record bearing and distance from the remaining original bearing tree:

A sawed Fir stump 40" dia., bears S.80°W., 23 lks. dist. marked with a rotted blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked

T31S
¼ S 33
S 4
T32S R4W
1959

from which new bearing trees:

A Fir 22" dia., bears N.9°E., 129 lks. dist., mkd. ¼ S33 BT.

A Cedar 18" dia., bears S.42½°W., 52 lks. dist., marked ¼ S4 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, J. Brady, crew - March 1966 - C.S. File 54/20-35

Found - No trace of brass cap set by Govt.
22" Fir now 19", N.9°E., 85.1 ft., shows good scar. (Find bearing to be N.4°E.)
18" Cedar now 22", S.42½°W., 34.3 ft. scribe visible ¼ S4 BT.

Set ¾" Iron rod at ¼ corner in creek bed.

Set Brass cap for Wit. Cor. mkd:

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33; and 4, T32-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

County Surveyors Office 1966
T31S Wit. Cor.
25' E. To
S 33 R
S 4 4W
T32S
New BTs -9" D.Fir N.29°W., 30.2 ft. scribed W.C. ¼ S33 CS BT.
23" D.Fir S.45¼°E., 6.0 ft. scribed W.C. ¼ S4 CS BT.

Fd. Cor. and Wit. Cor., BLM resurvey by Roseberry and Evans, Group #778, surveyed July/Sept. 1972 (DCSO records, Vol. 38 Pages 15467-68)