

PRIMARY CORNER DESCRIPTION NW 1/16 Sec. 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas County Surveyors Office - George J. Wenderoth - Dec. 1947 - C.S. File 40/29 and M 4-75

Set 1" Iron pipe, from which
18" Fir N.56°56'E., 60.3 ft.
28" Fir N.11°39'E., 60.1 ft.

BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15490)

Point for the NW 1/16 sec. cor. of sec. 27 at intersection with the E & W center line of the NW¼ of sec. 27.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd: NW 1/16 S 27
1972

from which the remains of the BTs mkd. by Wenderoth in 1947
A Fir stump, 28" dia., bears N.12½°E., 82½ lks., with scribe marks S BT visible on partially healed blaze.
A Fir stump, 23" dia., bears N.61 3/4°E., 88½ lks., no marks visible on open & decayed blaze.

and new BTs
A Madrone, 8" dia., bears S.51°E., 21½ lks., mkd: NW 1/16 S27 BT.
A Fir, 6" dia. bears N.27½°W., 28 lks. mkd: NW 1/16 S27 BT

From this point a local corner established & recorded by Wenderoth in 1947 bears S.8°50'E., 0.105 chs. monumented with an iron pipe, 1" dia., firmly set, protruding 10" above ground. This corner point was not accepted because its position is based on Wenderoth's ¼ sec. corner of secs. 26 & 27, which was not utilized.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 4/5/2001 - C.S. File 66/21-4

Found - 1972 BLM BC/IP, protrudes 5" out of ground.
8" now 12" high rotted Madrone stump with visible scribing "W 1/16 S27 B" bears S.51°E., 14.2 ft. (1972)
6" now 13" dia., D.Fir with a fully healed single blaze bears N.27½°W., 18.5 ft. (1972)

New - DCSO 5/8" x 30" long iron rod w/alum. cap protrudes 5" out of ground, bears North 4.88 ft.
1" I.D. iron pipe protrudes 6" out of ground bears S.8 3/4°E., 6.9 ft. (1947)
11" dia., D.Fir double blazed & scribed "NW 1/16 S27 CS BT" bears N.73°E., 13.6 ft.