

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 460200

PRIMARY CORNER DESCRIPTION East 1/16 Cor betw Secs 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Geo. J. Wenderoth, Deputy -
For: Cantleberry & R. Head, Feb. 1949 and Oscar Head, Sept.
1958 - M 12-56

Set 1" I.Pipe, from which
14" Madrona, N.20°W., 95.7 ft.
7" Pine, N.66°40'E., 91.3 ft.

BLM Resurvey by Lynn M. Roseberry and Larry D. Evans,
Cadastral Surveyors, under Group #778, surveyed July/Sept.
1972- (DCSO records Vol. 38 Page(s) 15475)

The E. 1/16 sec. cor., established and recorded by Wenderoth
in 1958, monumented with an iron pipe, 1" dia., firmly set,
protruding 8" above ground, from which bearing trees mkd. by
Wenderoth:

A Ponderosa Pine 10" dia., bears N.72 3/4°E., 138 lks.,
dist. with healed blaze.

A Madrone 17" dia., bears N.20½°W., 146 lks. dist., with
scribe marks S /16 BT visible on partially healed
blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground,
directly over iron pipe, with brass cap mkd:

E 1/16 $\frac{S\ 27}{S\ 34}$
1972

Douglas Co. Surveyors Office - J.R. Lundeen, Deputy - Wit: S.
Flause - June 28, 1984 - C.S. File 62/52-12

REFERENCE OUT CORNER ONLY

Found - 3/4" USBLM cadastral brass survey cap on 2½" x 28"
pipe, protruding 8" above ground and properly
stamped from 1972 resurvey.

Inside BLM cap and pipe monument is a 1" x 30" long
iron pipe from Wenderoth survey.

12" (Rec. 10") dia., Ponderosa Pine bears N.72
3/4°E., 91.1 ft., well healed double blaze, no
scribing found.

24" (Rec. 17") double trunk Madrone stump,
protruding 18" above ground. Portion of lower
scar remains but no scribing visible, bears
N.10½°W., 95.7 ft. (Rec. N.20½°W., and 96.4 ft.)

1¼" Iron pipe bears N.39¼°E., 2.23 ft. (not of
record)

(Above trees originally marked by Wenderoth in survey M 12-
56. New bearings and distances were recorded in BLM resurvey)

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 460200

PRIMARY CORNER DESCRIPTION East 1/16 Cor. for Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New Accessories:

11" dia., D.Fir scribed E 1/16 CS BT bears N.28½°E.,
59.0 ft.

The BLM split pipe monument with cap was dug up by this office. It will be reset in a monument box in the road when it is paved at the end of summer 1985. We set two iron rods on line with BTs using theodolite and meas. angle between trees. Fence corner post, 1" x 1" x 7', bears N.70°W., 1.5 ft. from corner.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - April 20, 1988 - C.S. File 62/52

(Recent realignment of Co. Rd. #36 has caused removal of all previous monuments)

Found - One BT originally recorded in Wenderoth survey. A record 10" dia., Pine now a 14" DBH Ponderosa Pine with a fully healed double blaze, bears N.72 3/4°E., 91.1 ft.

NW. Madrone BT removed during road alignment.

An 11" dia. D.Fir now a 12" DBH D.Fir with a partially healed double blaze with the scribing "E 1/16 CS BT" visible, bears N.28½°E., 59.0 ft.

A 5/8" dia. Iron rod with an alum. cap stamped "B0 1" set flush with ground bears N.28½°E., 53.38 ft.

A 5/8" dia. Iron rod with a alum. cap stamped "B0 2" set 3" below ground bears N.72 3/4°E., 59.89 ft.

We reestablish corner at referenced position by intersection distances and bearings recorded to bearing objects. The measured angle between the bearing objects is checked from the corner position and is found to agree with record. The reestablished corner position now falls in asphalt so top of spike is set flush with surface. Top of boat spike is marked "E 1/16 27/34"

New Accessory:

A 3" dia. Doug. Co. Public Works Dept. disk stamped "GR 5 BM" is set in a 6" I.D. concrete filled plastic pipe protruding 2" above ground bears N.88½°E., 51.78 ft.

Location in West bound lane of Co. Rd. #36 near easterly end of Galesville.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/2/2024 - C.S. File 67/57-55

Found - OBT, 23" P.Pine (rec N.72¾°E. 91.1 ft) Blaze not vis
continued next page

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 460200

PRIMARY CORNER DESCRIPTION East 1/16 Cor. betw. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

18" D.Fir, with fully headed double blaze, (Rec. N.28½°E., 59.0 ft)
5/8" iron rod with cap, B0 1 (rec. N.28½°E., 53.38 ft.)
5/8" iron rod with cap, B0 2, 4" below ground (rec 3") (rec. N.72¾°E., 59.89 ft.)
Spike (noted in 1988 record) gone due to rd resurfacing.
Note - All accessories FD in good condition, did not check bearings and distances.