

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7794)

-----  
Set a Fir post 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. mkd. ¼ S on W. face; from which

A Fir 10" dia., bears N.50°W., 17 ¾ lks. dist. mkd. ¼ S BT.

A Fir 10" dia., bears N.12¼°E., 11 lks. dist. mkd. ¼ S BT.

-----  
Survey by John H. Markham, Jr. - Wit: R.G. Boyd - For: Stomar Lumber Co. - April 28, 1959 - C.S. File 42/391-21

-----  
At midpoint, SET 5/8" x 30" Iron rod, from which  
7" Laurel bears S.45°E., 18.5 ft. mkd. ¼ S19 T31S R3W BT.

10" Fir bears S.75°E., 9.3 ft. mkd. ¼ S19 X BT.

5" Fir bears N.58°W., 12.5 ft. mkd. ¼ S24 BT.

5" Laurel bears West 20.3 ft. mkd. ¼ S24 T31S BT.

Road bears North 340.0 ft.

-----  
David Edwards - For: Roseburg Resources Co. - Feb. 2011 - M162-12

-----  
Set - 5/8"x30" steel rebar with 2½" dia., alum cap mkd. as per BLM manual and marked "ROSEBURG RESOURCES CO" "LS 2339" "2011"

An 8" dia. Cedar bears S.34°E., 17.6 ft.

An 8" dia. Madrone bears N.7°1W., 14.1 ft.

A 6 ft steel post is set 2' west.

The 5/8" dia. IR per C.S. 42/391 bears S.17°52'32"E., 52.28'.

Note- (Set E¼ Corner by proportionate measure) Monuments set by Markham in 1958 (see field notes in C.S. file 42/391 ), are significantly out of position and are therefore disregarded.