

PRIMARY CORNER DESCRIPTION AP (Line Tree on West Line Sec. 7)

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

Original - Geo. W. Hyde, Deputy Surveyor under contract No. 54, dated Feb. 19, 1855. (DCSO records Vol. 19 Page(s) 7877)

South on West boundary of sec. 7 ... @ 19.1 chains a Fir 30" dia.

Greg Lang for Silver Butte Timber Co. Oct. 1997 - M 128-18

Found - 42" Fir, broken top, original line tree, two marks on each side.

New Accessories -

Spike in face of 8" Fir, bears S.78°14'W., 21.19 ft.
scribed "LT T31S R6W S12" "BT"

Spike in face of 11" Fir, bears N.28°51'E., 22.32 ft.
scribed "LT T31S R5W S7" "BT"

Spike in face of 8½" Fir, bears S.59°31'E., 36.71 ft.
scribed "LT T31S R5W S7" "BT"

5/8" iron rod with plastic cap marked "Lang Surveying"
bears N.0°52'E., 5.00 ft.

BLM dependent resurvey by Daniel E. Weller, Cadastral Surveyor, under Group #1884, surveyed July/Sept 1998. (DCSO records Vol. 53 Page(s) 20474)

An original line tree, a fir, 42" diam., mkd. with two notches on N. and S. side, perpetuated by Lang, in 1998. This now becomes an Angle Point, from which a reference monument and bearing trees by Lang:

An iron rod, 5/8" dia., firmly set, projecting 3" above ground, bears N.0°52'E., 7½ lks., with plastic cap mkd. LANG SURVEYING.

A fir, 12" dia., bears N.30¼°E., 34½ lks., with scribe marks LT S7 T31S R5W BT visible on partially healed double blaze.

A fir, 9" dia., bears S.59½°E., 57 lks., with scribe marks LT S7 T31S R5W BT visible on partially healed double blaze.

A fir, 9" dia., bears S.77¼°W., 32½ lks., with scribe marks LT S12 T31S R6W BT visible on partially healed double blaze.