

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. cor. for 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7928)

Set a Maple post, 4 ft. long, 4" square, 20" in ground for the cor. to secs. 8,9, 16 and 17, marked T31S R5W S9 on the NE. face, S16 on the SE. face, S17 on the SW. face, S8 on the NW. face, also four notches on the South and four notches on the East angles of same, from which

A Chinquapin 7" dia., bears N.25°E., 21 lks. marked T31S R5W S9 BT.

A Dogwood 4" dia., bears S.21°E., 13 lks. dist. marked T31S R5W S16 BT.

A Maple 6" dia., bears S.65°W., 30 lks. dist., marked T31S R5W S17 BT.

A Chinquapin 5" dia., bears N.12°W., 11 lks. dist., marked T31S R5W S8 BT.

Survey by Victor S. King - For: Bate Lumber Co. - Oct. 30, 1959 - C.S. File 51/56-3

Found - Orig. BT, 6" Dogwood, S.21°E., 13 lks. with the overgrowth showing scribed BT. The overgrowth was so fragile that it would deteriorate almost immediately in the weather, so it is retained in our office for evidence.

Set 1" Pipe 36" long, 24" in ground in a mound of stones.
New BTs -48" Fir N.29°W., 39.5 ft. bark scribed S8 T31S R5W BT.

12" W.Fir S.41½°W., 10.7 ft. scribed S17 T31S R5W BT.

18" Fir S.64½°E., 86.5 ft. scribed S16 T31S R5W BT.

24" W.Fir N.69½°E., 8.7 ft. scribed S9 T31S R5W BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Joe Brady - May 1966 - C.S. File 54/25-19

Found - 1" Iron pipe at corner.
Orig. 6" Dogwood, now dead, S.21°E., 7.9 ft.
48" Fir N.29°W., 39.5 ft. bark scribed 'T31S R5W S8 BT" faint.

18" Fir now 21", S.64½°E., 86.5 ft.

12" Fir now 14", S.41½°W., 10.7 ft.

24" W.Fir N.69½°E., 8.7 ft. face rotten on this tree.

All BTs have recently been opened, but OK., with exception of one.

New BT - 28" D.Fir N.86°E., 56.0 ft. scribed T31S R5W S9 CS BT.
(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Reblazed and rescribed:
48" Fir N.29°W., 39.5 ft. scribed T31S R5W S8 CS BT.
Corner now lies in cutting corner.

BLM Corrective Resurvey - John Jelley, Lynn Roseberry, Floyd Brooks, Under Group #s 320 and 614, - Surveyed June 1966 through May 1968. (DCSO records Vol. 35 Page(s) 14368)

The Sec. Cor., perpetuated and recorded by V.S. King in 1959, monumented with an iron pipe, 36" long, 1" dia., firmly set 30" in the ground, from which the remaining original bearing trees:

A Dogwood stump, 8" dia., bears S.21°E., 13 lks. dist., with no marks remaining.

and bearing trees mkd. by King in 1959:

A W.Fir 25" dia., bears N.69½°E., 13 lks. dist., with scribe marks S9 T31SR5W BT visible on open blaze.

A W.Fir 20" dia., bears S.64½°E., 129 lks. dist., with a healed blaze.

A W.Fir 12" dia., bears S.41½°W., 16 lks. dist., with scribe marks S17 T31S R5W BT visible on open blaze.

A Fir 56" dia., bears N.29°W., 58½ lks. dist., with scribe marks RS 442 S8 T31S visible on bark. Remarkd T31S R5W S8 CS BT by County Surveyor in 1966.

and a bearing tree mkd. by the County Surveyor in 1966:

A Fir 30" dia., bears N.85°W., 85 lks. dist., with scribe marks T31S R5W S9 CS BT visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. dia., 24 ins. in the ground, with brass cap mkd:

S 8	S 9
S 17	S 16
1966	

Deposit the iron pipe alongside the iron post.

Brass cap and BTs found OK. (DCSO 1966 BT, called N.85°E., and 1966 Cadastral survey called N.85°W., is found to be N.85°E.) BLM resurvey by Berry and Akin, 1972-73 (DCSO records, Vol. 38 Pages 15686-87)

Ron Quimby - Crew: N. Fromdahl & L. Heddens - 2/2020 - C.S.
File 65/104-49

Found - BLM brass cap (properly mkd)
22" W.Fir S.41½°W., 10.6 ft. good scar.
70 Fir N.29°W., 38.6 ft. vis. bark scribes
40" Fir N.85°E., 56.1 ft. good scar. Cont.

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. cor. for 8, 9, 16 and 17

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

New - Alum posts 2' east & 2' North
Note - Area badly burnt 2019
Compass decl. 15½°E.